

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

5a. Indicate Type of Lease
State ☒ Fee ☐
5. State Oil & Gas Lease No.
V-642

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER-
2. Name of Operator
SPENCE ENERGY COMPANY
3. Address of Operator
381 Two Energy Square, 4849 Greenville Ave., Dallas, Texas 75206
4. Location of Well
UNIT LETTER M 330 FEET FROM THE South LINE AND 330 FEET FROM
THE West LINE, SECTION 14 TOWNSHIP 9S RANGE 32E NMPM.

7. Unit Agreement Name
8. Farm or Lease Name
STATE 14
9. Well No.
1
10. Field and Pool, or Wildcat
S.R.R. Devonian

15. Elevation (Show whether DF, RT, GR, etc.)
12. County
LEA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ OTHER ☐
SUBSEQUENT REPORT OF:
REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐ OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set C.I.B.P. at 11,000' with 40 ft. of cement on top. Set cement plug at 7100'.
Cut casing at 3827' and set a plug with 50 sxs. Went up 450' to 3377' and set
plug with 35 sxs. Tagged plug and plugged surface with 10 sxs.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Clay Spence TITLE Field Supervisor DATE 5/13/87
APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE 5/13/87