

10. COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. LG-1041	

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Stallworth Oil & Gas		8. Farm or Lease Name Kellahin 14 State
3. Address of Operator 407 West Missouri Avenue, Midland, Texas 79701		9. Well No. 1
4. Location of Well UNIT LETTER 1 , 810 FEET FROM THE East LINE AND 1980' FEET FROM THE South LINE, SECTION 14 TOWNSHIP 9-S RANGE 32-E NMPM.		10. Field and Pool, or Wildcat South Flying M Perm
15. Elevation (Show whether DF, RT, GR, etc.) 4328' GL		12. County Lea

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐
OTHER ☐

PLUG AND ABANDON ☒
CHANGE PLANS ☐
OTHER ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOBS ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐
OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug and abandon; formation tops: Salt 1680', Yates 2258', Queen 2940', San Andres 3480', Glorieta 4880', Clearfork 5642', Tubbs 6340', Abo 7184', Wolfcamp 8226', Three Brothers 8624', Bough "C" 8860'. Original total depth 10,695', PBTD 9009', 5-1/2" casing perforated from 8860-8880'. Set cast iron bridge plug at 8810', 35' cement on top C.I.B.P. Pull approximately 6000' + casing, 100' cement plug at stub of 5-1/2" casing, 100' plug at Glorieta if uncovered, 100' cement plug in and out shoe 8-5/8" casing set at 3760'. Pull approximately 1200' + 8-5/8" casing, 100' cement plug by 2-3/8" tubing at stub, 100' cement plug at Salt if uncovered, 100' plug in and out surface casing set at 396', 10 sack plug at surface and proper dry hole marker. Hole will be loaded with 9# mud laden fluid. Work to start May 1, 1975.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED **Rubert V. Gorman** TITLE **Field Superintendent** DATE **4-22-75**

APPROVED BY **Joe D. Ramsey** TITLE **Dist. I, Supv.** DATE **4-22-75**
CONDITIONS OF APPROVAL, IF ANY