

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name	
2. Name of Operator Dwight A. Tipton		8. Farm or Lease Name Robinson "14"	
3. Address of Operator P. O. Box 755, Hobbs, New Mexico 88241-0755		9. Well No. 1	
4. Location of Well UNIT LETTER <u>P</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM <u>East</u> <u>14</u> TOWNSHIP <u>9S</u> RANGE <u>33E</u> NMPM.		10. Field and Pool, or Wildcat Wildcat SanAndres	
15. Elevation (Show whether DF, RT, GR, etc.) 4341 GR		12. County Lea	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input checked="" type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Reentered 4/19/88. Drilled out plugs and circulated hole clean to 5040.
Ran 5½" 17# K-55 casing to 5040 and cemented with 500 sacks class C,
50/50 Pozmix, 2% gel, 2500# salt. Plug down 1:00 AM 4/23/88. WOC 57 hours.
Perf 4616-24 with 2 shots per foot. Treated with 500 gallons 15% MCA acid.
Swab load, ran rods & pump. 5/14/88 pump 21 bbls oil, 107 bbls water,
12 MCF gas 24 hours.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wanda Hall TITLE Agent DATE 5/23/88

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

MAY 24 1988

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: