

STATE OF NEW MEXICO
ENERGY AND MINERALS DEPARTMENT

OIL CONSERVATION DIVISION
P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

API #30-025-30400

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
LG 5182	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. <input type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P&A	7. Unit Agreement Name Echols State Unit
2. Name of Operator Yates Petroleum Corporation	8. Farm or Lease Name Echols State Unit
3. Address of Operator 105 South 4th St., Artesia, NM 88210	9. Well No. 3
4. Location of Well UNIT LETTER M 330 FEET FROM THE South LINE AND 990 FEET FROM THE West LINE, SECTION 9 TOWNSHIP 11S RANGE 38E NMPM.	10. Field and Pool, or Wildcat E. Echols Devonian
15. Elevation (Show whether DF, RT, GR, etc.) 3903.7' GR	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 11810'. Verbal permission obtained from Eddie Seay, NMOCD, Hobbs, NM, to plugback as follows:

Plug #1: 11810-11710' w/30 sacks Class H w/1% WR-15.

Plug #2: 11450-11350' w/30 sacks Class H w/1% WR-15.

Plug #3: 10150-10050' w/80 sacks Class H Neat. Tagged cement at 10080'.

Drilled cement 10080-10090'. PBDT 10090'.

8-6-88. Verbal permission obtained from A. R. Sadler, NMOCD, Hobbs, NM, to plug and abandon well as follows:

Plug #1 9146-9046' w/50 sacks Class H

Plug #2 7174-7074' w/60 sacks Class H

Plug #3 4570-4470' w/50 sacks Class H (across 8-5/8" shoe.)

Plug #4 2330-2230' w/30 sacks Class H

Plug #5 Surface w/10 sacks Class H

Plugging completed 8-7-88.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Richard D. Sadler*

TITLE Production Supervisor

DATE 8-10-88

APPROVED BY *Jack Griffin*

OIL & GAS INSPECTOR

TITLE

DATE MAY 11 1989

CONDITIONS OF APPROVAL, IF ANY: