

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.	30-025-30566
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	291-310 (E-26) 291-312 (OG-1402)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name "OG" State "OG"
2. Name of Operator LBO New Mexico, Inc.	8. Well No. 1
3. Address of Operator 4101 Birch St., Ste. 130, Newport Beach, CA 92660	9. Pool name or Wildcat North Bagley Wolfcamp Permian Penn
4. Well Location Unit Letter K : 2065 Feet From The South Line and 2010 Feet From The West Line Section 9 Township 11 South Range 33 East NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3288.8 (GR)	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

3/27-29/89: TD 8804', PBTD 8758'. Clean off location. RU pulling unit. GIH w/4-3/4" bit, csg scraper & 280 jts 2-3/8" EUE 8Rd J-55 tbg. TAC FC @8758'. Circ hole clean w/2% KCl wtr. POH with tbg. RU wireline. Run GR/CCL log. Perforate Wolfcamp 8708-20' (2 SPF) 24 holes w/4" csg gun. GIH w/5-1/2" pkr & 2-3/8" tbg (test in hole to 5000 psi). RU acidizers and acidize Wolfcamp w/3000 gallons 15% HCl and 35 ball sealers at 3 to 5 BPM. Flush w/2% KCl water. RU swab, swabbed & flowed 87 BO + load water.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Donald A. Turner TITLE Agent DATE 4-04-89
TYPE OR PRINT NAME Donald A. Turner TELEPHONE NO. 915/682-3418

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON
DISTRICT I SUPERVISOR

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL _____

APR 7 1989

100-100000

RECEIVED

APR 6 1989

OCD
HOBBS OFFICE