

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-30689
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Notice or Unit Agricultural Notice
McGuffin
8. Well No. 1
9. Pool Name or Willard South Flying M Bough

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐	2. Name of Operator Manzano Oil Corporation 505/623-1996	3. Address of Operator P.O. Box 2107/Roswell, NM 88202-2107
4. Well Location Unit Lease <u>K</u> : <u>2050</u> Feet From The <u>South</u> Line and <u>2030</u> Feet From The <u>West</u> Line Section <u>24</u> Township <u>9S</u> Range <u>32E</u> NMPH <u>Lea</u> County <u></u>		
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4344.9 GL		

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11/01/89 Received verbal approval to plug & abandon well from Paul Kautz.
11/04/89 Day 28. TD @ 9100'. Set cement plugs as follows:
100' plug at top of Bough "C" @ 9000' - 35 sks
100' plug at top of Abo @ 7272' - 35 sks
100' plug at top of Glorieta @ 4962' - 35 sks
100' plug at top of San Andres @ 3567' - 35 sks
100' plug at 1885' - 50' in and 50' out of 8-5/8" surface casing set
@ 1835' - 35 sks
10 sks surface plug
Cut off well head. Set dry hole marker.

I hereby certify that the information above is true and accurate to the best of my knowledge and belief.

SIGNATURE Alison Koff TITLE Production Clerk DATE 11/10/89
TYPE OR PRINT NAME TELEPHONE NO.

(This space for State Use)

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE AUG 08 1991
CONDITIONS OF APPROVAL, IF ANY: