

MARTIN YATES, III
1912 - 1985
FRANK W. YATES
1936 - 1986



105 SOUTH FOURTH STREET
ARTESIA, NEW MEXICO 88210
TELEPHONE (505) 748-1471

S. P. YATES
CHAIRMAN OF THE BOARD
JOHN A. YATES
PRESIDENT
PEYTON YATES
EXECUTIVE VICE PRESIDENT
RANDY G. PATTERSON
SECRETARY
DENNIS G. KINSEY
TREASURER

DRILL STEM TESTS

WOODSTOCK STATE UNIT #1, V-1259
Unit P, Sec. 5-T9S-R33E
Lea County, NM

DST #1 8630-8493' Lower Abo: Opened with weak blow, 1/4" in bubble bucket and continued throughout. Closed tool in 30 mins with weak blow. SI 60 minutes. Opened with weak blow, died in 10 minutes. Closed tool in 60 minutes. SI 180 minutes. Reopened for 3rd flow, dead throughout. RECOVERY: 60' drilling mud, 168000 CL. SAMPLER: 1050 cc rat hole mud with 75 psi, 168000 CL. PRESSURES: IHP 4664, 30 min IFP 96-109, 60 min ISIP 1028, 60 min 2nd FP 121-121, 180 min FSIP 1996, 60 min FFP 121-121, FHP 4646.

DST #2 9291-9361' (71') Bough C: TO 30", SI 60", TO 60", SI 180". Opened tool, to bottom of bucket in 1 min. Pressure increased from 15 psi to 68 psi. SI. GTS in 2 mintues. Opened tool on 1/4" choke. Pressure increased from 21 psi to 85 psi. SI. RECOVERY: 1237' gas cut mud and water with foamy emulsion. SAMPLER: 2.4 cfg, 280 cc oil, 550 cc water with pressure 390 psi. PRESSURES: IHP 5030, IFP 293-381, ISIP 2252, FFP 238-586, FSIP 2002, FHP 5002.