

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30 025 30858
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-2174
7. Lease Name or Unit Agreement Name State "26"
8. Well No. 3
9. Pool name or Wildcat Vada (Devonian)

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Western Reserves Oil Company Inc.	
3. Address of Operator P. O. Box 993, Midland, TX 79702	
4. Well Location Unit Letter <u>K</u> : <u>1650</u> Feet From The <u>south</u> Line and <u>2310</u> Feet From The <u>west</u> Line Section <u>26</u> Township <u>10S</u> Range <u>33E</u> NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4195.8' GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <u>Prep to commence sidetrack</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <u>SI</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

11-01-95: MIRU Pride Well Service. Prep to pull production string & submersible pump in am.

11-02-95: Unflange tubing head. Commence TOH w/tubing (laying down in singles) & spooling up sub pump cable. Break down sub pump & send to Reda Pump, Midland, TX for storage. Send cable to Cable Services, Hobbs, NM. Rig up Halliburton Services wireline. Run 4½" gauge ring w/junk basket to 12,641' KB elev. POH. RIH w/5½" CIBP & set @ 12,614' KB elev. POH. Rig down wireline. SION.

11-03-95: Release well service unit. Prep to move in workover rig & commence whipstock & directional sidetrack work around 11-09-95.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Christopher P. Renaud TITLE Engineer DATE 11-03-95
TYPE OR PRINT NAME Christopher P. Renaud TELEPHONE NO. 915 683-5533

(This space for State Use)

ORIGINAL SIGNED BY
GARY WINK
FIELD REP. II

APPROVED BY _____ TITLE _____ DATE NOV 08 1995

CONDITIONS OF APPROVAL, IF ANY:

