

RECEIVED

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals

5. Lease Designation and Serial No.

USA NM 68823

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Federal 3C #2

9. API Well No.

30-025-30978

10. Field and Pool, or Exploratory Area

Milnesand Abo

11. County or Parish, State

Lea County, NM

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

Knox Industries, Inc.

3. Address and Telephone No.

P.O. Box 3023 Midland, Texas 79702

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

660' FNL & 1880 FWL Sec. 3, T-9-S, R-35-E

12. CHECK APPROPRIATE BOX(S) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

- ☐ Notice of Intent
☒ Subsequent Report
☐ Final Abandonment Notice

TYPE OF ACTION

- ☐ Abandonment
☐ Recompletion
☐ Plugging Back
☐ Casing Repair
☐ Altering Casing
☐ Other
☐ Change of Plans
☐ New Construction
☐ Non-Routine Fracturing
☐ Water Shut-Off
☐ Conversion to Injection
☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Obtained approval from BLM and OCD to deepen the well and to commingle production from the Abo and Bough "C" formations.
1/4/93 - Rigged up Pool Well Servicing Rig and foam air drilling equipment. Drilled out cement in shoe joint of 5 1/2" casing and drilled shoe at 9740'. Drilled formation to 9805' (Bough "C"). Hole kept filling up with chunks of formation. Rigged up reverse drilling unit. Reverse out chunks of formation. Could not keep hole clean. Lost circulation. Set Cast Iron Bridge Plug at 9600' in 5 1/2" casing. Returned well to production in the Abo Formation. Could not complete in the Bough "C".

14. I hereby certify that the foregoing is true and correct

Signed David R. Glass

Title Production Supervisor

Date 1/22/93

(This space for Federal or State office use)

(OPIC SGDA DAVID R. GLASS

Approved by
Conditions of approval, if any:

Title

Date

Title 18 U.S.C. Section 1001 makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representation.

*See Instruction on Reverse Side