

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

30-025-31074

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:

OIL
WELL ☒

GAS
WELL ☐

OTHER

2. Name of Operator

MARALO, INC.

3. Address of Operator

P. O. BOX 832, MIDLAND, TX 79702

8. Well No.

1

9. Pool name or Wildcat

JENKINS; SAN ANDRES

4. Well Location

Unit Letter **J** : **1980** Feet From The **SOUTH** Line and **1980** Feet From The **EAST** Line

Section **19** Township **9S** Range **35E** NMPM **LEA** County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4176' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☒

REMEDIAL WORK ☐

ALTERING CASING ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☐

PULL OR ALTER CASING ☐

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

CURRENT
PERFORATION: 4767' - 4787'

CASING:

13 3/8" 48#
8 5/8" 24# & 28#
4 1/2" Liner

@ 495' w/530 sx circ
@ 4105' w/1250 sx circ-
@ 3,826' - 5337' w/425. Drid out cmt to 5139' PBTD

PROPOSED
OPERATION: Plug and Abandon

1. Notify New Mexico Oil Conservation Commission, Hobbs, New Mexico (505) 393-6161.
2. RUPU. RIH w/CIBP on wireline set @ $\pm 4750'$. Cap with cement. (min 5 sx).
3. PU workstring, RIH to $\pm 4700'$, circ & load hole w/10#/gal mud-laden fluid using 25#/bbl.
4. Set 100' cmt plug 4055' - 4155' across base 8 5/8" csg (min 45 sx).
5. Set 100' cmt plug 445' - 545' across base 13 3/8" csg (min 35 sx).
6. Set surface plug, install dryhole marker, clean location.

LOG TOPS & EXISTING PLUGS:

Top salt - 2200'
Base salt - 2757'
Grayburg - 4076'
San Andres - 4140'
Abo - 7735'
Bough C - 7735'
Miss - 11,917'
Devonian - 12,630'
Cmt plug @ 12,652' w/50 sxs
Cmt plug @ 11,231' w/50 sxs
Cmt plug @ 8,986' w/50 sxs
Cmt plug @ 5,461' w/60 sxs

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Dorothea Logan

TITLE

REGULATORY ANALYST

DATE

MARCH 9, 1998

TYPE OR PRINT NAME

DOROTHEA LOGAN

TELEPHONE NO. **(915) 684-7441**

(This space for State Use)

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

ORIGINAL SIGNED BY CHRIS WILLIAMS
DISTRICT I SUPERVISOR

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL IF ANY:

THE COMMISSION MUST BE NOTIFIED 24
HOURS PRIOR TO THE COMMENCEMENT OF
PLUGGING OPERATIONS FOR THE CASE
TO BE APPROVED.