

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31104
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. LG-1041
7. Lease Name or Unit Agreement Name Kellahin State (14)
8. Well No. 4
9. Pool name or Wildcat South Flying M-Bough

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	
2. Name of Operator Spence Energy Co.	
3. Address of Operator 4849 Greenville Ave Ste#381 Dallas, Tex. 75206	
4. Well Location Unit Letter P : 980' Feet From The South Line and 330' Feet From The East Line Section 14 Township 9 South Range 32 East NMPM Lea County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4336.4 G.L.	

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☒
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work Performed under Jacks Supervision 4/16/92 - 4/23/92

- 1) Loaded hole w/ Mud.
- 2) Set 100' Plug @ 8400'
- 3) Set 100' Plug @ 6360'
- 4) Attempted to cut casing @ 5917', But would not come. Cut again @ 5475' & Started to pull casing out. I was instructed to set a plug from 5917' to 5475' plus 50' out of 5475', & did.
- 5) Set 100' Plug @ 2200'
- 6) Set 100' Plug @ 1740'
- 7) Set 10 Sack plug @ surface.
- 8) all plugging has been completed plus a dry hole marker installed.

~~99~~ All 8 5/8" casing is left in well & the casing cut of is 4 1/2"
~~& there is still 3475' of 4.5 left in well.~~

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Clay Spence TITLE Vice President DATE 6-1-92
TYPE OR PRINT NAME Clay Spence

TELEPHONE NO. 214-739-0027

(This space for State Use)

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE MAR 16 1993

CONDITIONS OF APPROVAL, IF ANY:

101°C

RECEIVED

JUN 08 1992

CD HOEBS OFF