

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1960, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31236
5. Indicate Type of Lease STATE ☐ FEE ☒
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Fullingim
8. Well No. #1
9. Pool name or Wildcat East Caprock Wolfcamp

10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4322' KB
--

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL ☒ GAS ☐ OTHER ☐	2. Name of Operator Manzano Oil Corporation 505/623-1996
3. Address of Operator P.O. Box 2107/Roswell, NM 88202-2107	4. Well Location Unit Letter N : 1980 Feet From The West Line and 660 Feet From The South Line Section 13 Township 12S Range 32E NMPM Lea County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☐
	CASING TEST AND CEMENT JOB ☐
	OTHER: Shooting & Acidizing ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

7-26-91 Acidized w/2000 gal - 20% NE/FE. Swab total 143 bbls/5hr (29 BPH) Have 46 bbls ovr load. No oil & little gas.

7-27-91 Set CIBP @ 9740'. Perf 9618'-30'=12' w/24 holes. Acidize w/1500 gal NE/FE acid + 36 balls. Swab 130 BF w/FL 5200'. No oil or gas Rec total 148 BF/5 hrs (29 bbls/hr). Have 50 bbls ovr load. SDON.

7-30-91 Ran CIBP on wireline. Set @ 9550'. Perf 9430'-35'=5' w/10 holes & 9438'-40'=2' w/4 holes. Acidize w/1000 gal 20% NE/FE + 24 balls

7-31-91 Swab to seat nipple, rec total 64 bbls. Small amt gas flared to pit. Wait 2 hrs, run swab - 30' fl IH. Did not get OOH w/fl. Set CIBP @ 9350'. Perf 8928'-38'=10' w/20 holes.

8-1-91 Spot 2000 gal 20% NE/FE to pkr w/25 balls. Swab bk 75 BLW. Well started flwg in hd.

I hereby certify that the information above is true and accurate to the best of my knowledge and belief.

SIGNATURE <u>Laura J. King</u>	TITLE <u>Production Analyst</u>	DATE <u>8/18/91</u>
TYPE OR PRINT NAME <u>Laura J. King</u>	<u>(505-623-1996)</u>	TELEPHONE NO.

(This space for State Use)

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: