

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Enc Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO. 30-025-31348
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. V-3417
7. Lease Name or Unit Agreement Name GOOD TEXIAN
8. Well No. 1
9. Pool name or Wildcat WILDCAT
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4320'GR - 4334'RKB

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <u>Re-entry</u>
2. Name of Operator THE EASTLAND OIL COMPANY
3. Address of Operator DRAWER 3488, MIDLAND, TX 79702

4. Well Location Unit Letter <u>G</u> : <u>1980</u> Feet From The <u>NORTH</u> Line and <u>1980</u> Feet From The <u>EAST</u> Line Section <u>26</u> Township <u>12-S</u> Range <u>32E</u> NMPM LEA County
--

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-14-15-92 Rig up & drill cement plugs @surface and at 1500', THH to 2660', displace hole w/2%KCL.

5-16-92---- Perforate 2477'-2499' w/20 holes. Acidize w/1600 gal. 15% NEFE acid test zone. Recovered 40 BLW, no oil.

5-19-92---- Set 8-5/8" CIBP @2473'. Perforate 2405'-2461' - 39 holes, acidized w/3000 gal. NEFE acid, tested zone, recovered 46 BLW & light skim oil.

5-21-92---- Displace hole w/mud-laden fluid, spot 35 sx class C cement w/2% CAC1 @2473', tag plug @2348'. Spot 25 sx plug @1607'. Spot 10 sx plug in surface.

5-22-92---- Move off rig and equipment, install dry hole marker.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Travis Reed TITLE PRODUCTION SUPERINTENDENT DATE 6/3/92
TYPE OR PRINT NAME TRAVIS REED TELEPHONE NO.

(This space for State Use)

APPROVED BY ORIGINAL SIGNATURE OF APPROVING OFFICIAL TITLE APPROVING OFFICIAL DATE AUG 05 1993
CONDITIONS OF APPROVAL, IF ANY: