

DISTRICT I  
P.O. Box 1980, Hobbs NM 88241-1980

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

## OIL CONSERVATION DIVISION

2040 Pacheco St.  
Santa Fe, NM 87505

WELL API NO. 30-025-31411		
5. Indicate Type of Lease STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>		
6. State Oil & Gas Lease No. NM-1202771		
7. Lease Name or Unit Agreement Name Apache		
8. Well No. 1		
9. Pool name or Wildcat Wildcat (San Andres)		
_____ Feet From The _____ West _____ Line		
NMPM	Lea	County

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER		Apache	
2. Name of Operator Bright & Company		8. Well No. 1	
3. Address of Operator 500 West Texas Ave., Ste. 1280, Midland, TX 79701		9. Pool name or Wildcat Wildcat (San Andres)	
4. Well Location Unit Letter <u>E</u> : <u>1650</u> Feet From The <u>North</u> Line and <u>990</u> Feet From The <u>West</u> Line Section <u>5</u> Township <u>9S</u> Range <u>34E</u> NMPM Lea County			
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 4307.2 GR		4321 KB	

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

**NOTICE OF INTENTION TO:**

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: \_\_\_\_\_ ☐

**SUBSEQUENT REPORT OF:**

REMEDIAL WORK ☐ ALTERING CASING ☐  
 COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐  
 CASING TEST AND CEMENT JOB ☐  
 OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. MIRU (Open perforations 4584-4692')
2. RIH w/ tbg to retainer @ 4730' spot 30 sx cmt. 4730-4484'. WOC & Tag.
3. Circulate w/ MLF, POOH w/ tbg.
4. Cut & pull 4008' of 5-1/2" casing.
5. RIH w/ tbg. to 4058', spot 30 sx 4058-3958. WOC & Tag. (Shoe, Stub Plug)
6. Spot 30 sx 2042-1942'. (Top Salt 2042').
7. Spot 30 sx 434-334'. (13-3/8" shoe).
8. 10 sx 10-3, Surface plug.
9. RDMO, perform reclamation. Install dry hole marker.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE WOOD TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kerim Massad TITLE Agent DATE 4-10-00

TYPE OR PRINT NAME Roger Massey TELEPHONE NO. (915) 570-7087

(This space for State Use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

CONDITIONS OF APPROVAL, IF ANY: