

Submit 3 Copies To Appropriate District Office
District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Ave., Artesia, NM 88210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
Revised March 25, 1999

WELL API NO.	30-025-35615
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>	
6. State Oil & Gas Lease No.	
7. Lease Name or Unit Agreement Name:	Largo 36 State
8. Well No.	#1
9. Pool name or Wildcat	Atoka

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other ☐ Injection

2. Name of Operator
Concho Oil & Gas, Corp.

3. Address of Operator
110 W. Louisiana, Ste 410 Midland, TX 79701

4. Well Location
Unit Letter G : 1980 feet from the North line and 1980 feet from the East line
Section 36 Township 10S Range 32E NMPM County Lea

10. Elevation (Show whether DR, RKB, RT, GR, etc.)
4299' GR

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: ☐

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompilation.

- MIRU, POH, LD rods & pump. NU BOP and POH w/ tbg.
- RIH open ended to 9112', spot plug #1 of 25 sxs cmt. If csg is to be pulled, POH w/ tbg, (if not), PUH to 6650' & spot plug #2 6650' - 6550'. POH.
- Perf 5-1/2" csg 3797'. RIH spot plug 3797' - 3700', tag plug #3. PUH to 1700', spot plug #4, 1700' - 1600'. PUH to 468', spot plug #5, (468' - 368' - tag). POH, spot 10 sx surface plug.
- Cut off csg header, weld on plate & install P&A marker.

NOTE: If csg (5-1/2") is pulled, place 50' in/50' out on csg stump. Continue setting plugs. Displace hole w/ 12.5# gelled 9.5 brine.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE C-103 TO BE APPROVED.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Kim Stewart TITLE Regulatory Analyst DATE 11/19/02

Type or print name Kim Stewart Telephone No. 915/ 683-7443
(This space for State use)

APPROVED BY _____ TITLE _____ DATE NOV 22 2002

Conditions of approval, if any:

ORIGINAL SIGNED BY
GARY W. WINK
OC FIELD REPRESENTATIVE II/STAFF MANAGER