

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-85

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
NA	
7. Unit Agreement Name	
M	
8. Farm or Lease Name	
John Gault SWD	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
12. County	
Roosevelt	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Disposal well
2. Name of Operator
Sage Energy Company
3. Address of Operator
P. O. Drawer 3068, Midland, Texas 79702
4. Location of Well
UNIT LETTER M, 660 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 25 TOWNSHIP 8S RANGE 36E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.)
NA

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plug No. 1 - 200 sx Class "H" cement at perfs 12,788', pressure tested to 200# held OK. Witnessed and OK'd by State Representative.  
Set retainer at 3478' pumped 100 sx.  
Plug No. 2 Set 100' plug at 2200'  
Plug No. 3 Set 100' plug at 1650'  
Perforated at 550', cemented with 325 sxs, circ to surface  
Plug No. 4 20' plug in 5½" at 550'  
Plug No. 5 10 sxs plug at surface, set marker P&A  
No pipe recovered.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Frances Holzgraf TITLE Production Clerk DATE June 27, 1985

APPROVED BY Jack Griffin TITLE OIL & GAS INSPECTOR DATE MAR 21 1988

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 28 1985

011  
HQB: [illegible]