

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
NA	
7. Unit Agreement Name	
M	
8. Farm or Lease Name	
John Gault SWD	
9. Well No.	
1	
10. Field and Pool, or Wildcat	
12. County	
Roosevelt	

SUNDRY NOTICES AND REPORTS ON WELLS <small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small>	
1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Disposal Well	
2. Name of Operator Sage Energy Company	
3. Address of Operator P. O. Drawer 3068, Midland, Texas 79702	
4. Location of Well UNIT LETTER <u>M</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>25</u> TOWNSHIP <u>8S</u> RANGE <u>36E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.) NA	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> TEMPORARILY ABANDON <input type="checkbox"/> PULL OR ALTER CASING <input type="checkbox"/> OTHER <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> COMMENCE DRILLING OPNS. <input type="checkbox"/> CASING TEST AND CEMENT JOB <input type="checkbox"/> OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Pull and rec. all possible tubing:

Plug No. 1 - 100' plug at perfs 12788', cut 5½" csg from free pt. - 9000'±
 Plug No. 2 - 100' plug at 5½" stub (1/2 in and 1/2 out) at 9000'±.
 Plug No. 3 - 100' plug at T/Wolfcamp - 8500'
 Plug No. 4 - 100' plug at T/Abo - 7380'
 Plug No. 5 - 100' plug at T/Glorieta - 5000'
 Plug No. 6 - 100' plug at 9 5/8" shoe (1/2 in and 1/2 out) at 4568'.
 Plug No. 7 - 100' plug at B/Salt 2100 in 9 5/8" csg.
 Plug No. 8 - 100' plug at T/salt 1650' in 9 5/8" csg.
 pull 9 5/8" from stub-in at 498.
 Plug No. 9 - 100' plug (1/2 in and 1/2 out) at 498.
 Plug No. 10- 100' plug at 13 3/8" shoe at 384.
 Plug No. 11 - 10 sx surface plug and P&A marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J. Halverson TITLE Production Clerk DATE April 19, 1985
 ORIGINAL SIGNED BY JERRY SEXTON
 DISTRICT 1 SUPERVISOR
 APPROVED BY _____ TITLE _____ DATE _____
 CONDITIONS OF APPROVAL, IF ANY:

APR 23 1985

RECEIVED

APR 22 1985

O.C.D.
HUMAN RIGHTS OFFICE