

10. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-7097
7. Unit Agreement Name
8. Farm or Lease Name State "AE"
9. Well No. 3
10. Field and Post, or Wildcat Allison-Penn.
12. County Roosevelt

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT - A" (FOR A C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- P & A
2. Name of Operator Atlantic Richfield Company
3. Address of Operator P. O. Box 1978, Roswell, New Mexico 88201
4. Location of Well UNIT LETTER N 660 FEET FROM THE South LINE AND 1980 FEET FROM THE West LINE, SECTION 36 TOWNSHIP 8-S RANGE 36-E N.M.P.M.
15. Elevation (Show whether DF, RT, GR, etc.) 4058' DF

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT C	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

This well has been plugged and abandoned in the following manner:

Attempted to run DR plug - unable to set DR plug in 415-D pkr due to salt and scale obstruction in bore of packer. Spotted 13 sk cement plug 9602-9495'. Shot off 5½" casing @ 4034' WLM. Pulled 124 jts (4010.72') of 5½" OD 8R csg. Spotted 40 sk cement plug 3902-4056. Put 10 sk cement plug in top of 8-5/8" casing. Installed dry hole marker. 8-5/8" and 11-3/4" casing strings remain intact. 9#/gal salt gel mud was used to spot all plugs.

Your office will be notified when location is ready for inspection.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>N.D. Dietrich</u>	TITLE <u>Dist. Dirg. Supervisor</u>	DATE <u>3/17/71</u>
APPROVED BY <u>Nathan E. Clegg</u>	TITLE <u>INSPECTOR</u>	DATE <u>MAR 17 1971</u>

CONDITIONS OF APPROVAL, IF ANY: