

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
BUREAU OF LAND MANAGEMENT

N. M. OIL GULF COMMISSION  
SUBMIT IN TRIPLICATE  
(Other instructions on re-  
lease designation and serial  
NM 021195)

Form approved.  
Budget Bureau No. 1004-1  
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

ARCO Oil and Gas Company

3. ADDRESS OF OPERATOR

P. O. Box 1610, Midland, Texas 79702

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

660' FSL & 1980' FWL, SE 1/4, SW 1/4

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Atlantic Federal

9. WELL NO.

1

10. FIELD AND POOL OR WILDCAT

Allison, East

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

28-8S-37E

12. COUNTY OR PARISH

Roosevelt

13. STATE

NM

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETION

ABANDON\*

CHANGE PLANS

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

SUBSEQUENT REPORT OF:

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.) \*

Cement top (PBTD) was tagged and drilled on at 7322'  
Cut off well head and cmt 7-5/8" x 10-3/4" annulus 0-50' w/60 sx "H" Neat cmt. Installed  
P&A marker and cleaned location.

- 0-470' Surf plug - Perf @ 470' (7-7/8" csg) could not circ to surf. Inj 100 sx  
"H" Neat & pump 200 sx "H" Neat w/1% CaCl<sub>2</sub> to surf.
- Cmt ret @ 2159' T.-Salt - Perf @ 2250'. Pmpd to 1100 psi w/no inj. set CICR @  
2159' and pmpd 300 sx "H" left 12 sx on top of CICR.
- 2676-2903' B-Salt - Perf @ 2840'. Pmpd to 2250 psi w/no inj. Pump 300 sx "H".
- 3900-4100' 7-5/8" csg - 35 sx "H" Neat cmt.
- 7100-7300' 4-1/2" csg shoe - Spotted 20 sx "H" Neat cmt

Well P&A 9-25-86.



18. I hereby certify that the foregoing is true and correct

915-688-5672

TITLE Engr. Tech. Spec.

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

10-23-86

APPROVED  
PETER W. CHESTER

DATE

APR 29 1993

BUREAU OF LAND MANAGEMENT  
ROSWELL RESOURCE AREA

\*See Instructions on Reverse Side