

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPLICATE*
(Other instruction re-
verse side)Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM 02218

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

H

8. FARM OR LEASE NAME

King Davis Federal

9. WELL NO.

4

10. FIELD AND POOL, OR WILDCAT

Allison Penn

11. SEC., T., R., M., OR BLM. AND
SURVEY OR AREA

33 8S 17E

12. COUNTY OR PARISH

Roosevelt

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL
WELLGAS
WELL

OTHER

2. NAME OF OPERATOR

Sam Boren

3. ADDRESS OF OPERATOR

Box 953, Midland, Texas

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

1984/7/16 660/E
1980 S 660 N Sec. 33

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4010 DF

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF



PULL OR ALTER CASING



FRACTURE TREAT



MULTIPLE COMPLETE



SHOOT OR ACIDIZE



ABANDON*



REPAIR WELL



CHANGE PLANS



(Other)



SUBSEQUENT REPORT OF:

WATER SHUT-OFF



REPAIRING WELL



FRACTURE TREATMENT



ALTERING CASING



SHOOTING OR ACIDIZING



ABANDONMENT



(Other)

(NOTE: Report results of multiple completion or Well
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

Well plugged as follows:

25 sax pumped down 4 1/2" csg. to 9500', 4 1/2" csg. shot @ 4785', pumped 25 sax down 4 1/2" csg. 7 5/8 shoe @ 4244 pumped 25 sax down 4 1/2" csg. @ 4263'; 7 5/8" csg. shot @ 1256', pumped 25 sax down 7 5/8" csg. 10 3/4 shoe @ 414, pumped 25 sax down 7 5/8" csg. @ 454'. 10 sax in top of 10 3/4" csg.

Steel marker erected. Will notify when ready for inspection.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Agent

DATE

3/1/66

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

APR 1 1966

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE: 1961-O-495229

647-881

Well plugged as follows:

32' sack pumped down 4 1/2" cas. to 8500', 4 1/2" cas. shot
4 1/2" cas. 7 5/8 shoe @ 4244' pumped 32' sack down 4 1/2" cas.
@ 1288', pumped 32' sack down 7 5/8" cas. to 344' shoe @ 414',
cas. @ 424'. 10' sack in top of 10 3/4" cas.

Steel marker erected. Will notify when ready for inspection

APR 2 11 14 AM '66

Box 953, Midland, Texas

1960 2 650 N Dec. 33