

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

SEP 23

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.  
**7737**

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name -
2. Name of Operator <b>Coastal States Gas Producing Company</b>	8. Farm or Lease Name <b>T. S. Massey</b>
3. Address of Operator <b>P. O. Box 235, Midland, Texas 79701</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>N</b> , <b>1980</b> FEET FROM THE <b>west</b> LINE AND <b>660</b> FEET FROM THE <b>south</b> LINE, SECTION <b>15</b> TOWNSHIP <b>8S</b> RANGE <b>36E</b> NMPM.	10. Field and Pool, or Wildcat <b>So. Prairie Penn</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>4098.6' GR</b>	12. County <b>Roosevelt</b>

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

**Well No. 1 was completed 2-17-62 in the Penn (9673-94').**

**Well No. 1 was plugged and abandoned 8-28-69 as follows:**

1. Pumped 30 sxs cement across perforations @ 9673 to 9674'. Pulled tubing.
2. Cut and pulled 1470' of 8-5/8" casing. Spotted 30 sxs cement @ 1470' on 8-5/8" stub.
3. Spotted 30 sxs cement in and out of 13-3/8" shoe @ 358'.
4. Cleaned out cellar, cut off surface head and spotted 10 sxs cement in top of surface casing.
5. Welded plate and installed dry hole marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Joe R. Howard TITLE Division Production Manager DATE 9-19-69

APPROVED BY John W. Runyan TITLE Geologist DATE 1970

CONDITIONS OF APPROVAL, IF ANY: