

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLIC
(Other instructions o.
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

LC 067192-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "J"

9. WELL NO.

2

10. FIELD AND POOL, OR WILDCAT

Prairie Cisco, South

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

23, T-8-S, R-36-E

12. COUNTY OR PARISH

Roosevelt

13. STATE

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

American Petrofina Company of Texas

3. ADDRESS OF OPERATOR

Box 1311, Big Spring, TX 79720

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Unit D, 660 FNL, 660 FWL, Sec. 23

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

(Other) ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

ABANDON* ☐

CHANGE PLANS ☐

SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐

FRACTURE TREATMENT ☐

SHOOTING OR ACIDIZING ☐

(Other) ☐

REPAIRING WELL ☐

ALTERING CASING ☐

ABANDONMENT* ☒

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)*

01-10-78 Set cast iron bridge plug at 9600' and dumped 3 sx. cement on top.
Set cast iron bridge plug at 8390' and dumped 3 sx. cement on top.
01-11-78 Cut 4-1/2" casing at 5680' but could not pull
01-12-78 Cut 4-1/2" casing at 4950' and laid down 30 jts.
01-13-78 Pulled remainder of 4-1/2" casing.
01-14-78 Ran tbg. and pumped mud. Set 50 sx cement plug at 4990'. Raised tubing
and pumped 50 sk plug at 4200'. Waited 4-1/2 hrs. and tagged plug at 4050'
Pumped 35 sk plug at 2350'.
01-17-78 Shot 3-5/8" casing at 1390', 523' and 490' but could not pull.
Shot 3-5/8" casing at 423' and pulled out.
01-19-78 Pumped 140 sk. cement plug at 450'
01-23-78 Tagged cement plug at 210'. Set 10 sk cement plug at surface and installed
4" pipe marker

PTA 1-23-78

18. I hereby certify that the foregoing is true and correct

SIGNED

J. C. Chapman

TITLE Asst. Dist. Mgr. of Production


2-1-73

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:



*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

U.S. GOVERNMENT PRINTING OFFICE : 1963 - O - 685229

847 - 485