Porm 9-331a (PED. 1601) APR 3 1962 (SUBMIT IN E. W. STANDLEY UNITED DISTRICT ENGINEER DEPARTMENT O GEOLOGIC Juspected C.K. for c	STATES F THE INTERIOR CAL SURVEY 3-29-62 28 Junt Job	4. 8. 876.7	890 \$ \$62
SUNDRY NOTICES ANI	SUBSEQUENT REPORT OF WATER SUBSEQUENT REPORT OF SHOOTING SUBSEQUENT REPORT OF ALTERING SUBSEQUENT REPORT OF RE-DRILL SUBSEQUENT REPORT OF ABANDON SUPPLEMENTARY WELL HISTORY	G OR ACIDIZING 3 CASING ING OR REPAIR	
(INDICATE ABOVE BY CHECK MARK NAT Well No. <u>1</u> is located <u>1,980</u> ft. from SW/4 NE/4, <u>31</u> <u>8-S</u> <u>38</u> (24 Sec. and Sec. No.) (Twp.) (Ran Undesignated Roosevelt (Field) (County or Sub The elevation of the derrick floor above sea level	February 25 N line and 1,980 ft. fror -E N.M. P (Meridian) Ne	,	

DETAILS OF WORK

(State names of and expected depths to objective sands; show sizes, weights, and lengths of proposed casings; indicate mudding jobs, cementing points, and all other important proposed work)

Used 10# mud in plugging operations; set 50 sx. cement plug from 9,400' to TD 9,501', set 40 sx. cement plug from 4,023' to 4,200' and a 17 sx. cement plug in top section of hole from surface to 60'. Left 401' of 13~3/8'' (48#) surface casing and 4,210' of 8~5/8'' (24#) intermediate casing in the hole. Mud pits filled, location levelled and cleared of junk and location properly marked.

I understand that this plan of work must receive approval in writing by t	he Geological Survey before operations may be commenced.	
Company David Fasken		
Address 608 First National Bank Bldg.,	\sim	
Midland, Texas	By (C. C. joy Title	Ì
Telephone No: MU 2-5285	Title Agent	
	100 1000 1000	