orm 9-331 N. H. DIL COHS. COM Dec. 1973 P. O. BOX 1980		Approved. It Bureau No. 42–R1424
UNITED STATES HOBBS, NEW MEX	CO 88240	
DEPARTMENT OF THE INTERIOR	<u>NM-060177</u>	
GEOLOGICAL SURVEY	6. IF INDIAN, ALLOTTEE OR TRIBE NAME	
SUNDRY NOTICES AND REPORTS ON WELLS	7. UNIT AGREEMENT N	AME
eservoir. Use Form 9-331-C for such proposals.)	8. FARM OR LEASE NAME	
1. oil gas	Shearn Federal	
well X well other	9. WELL NO.	
2. NAME OF OPERATOR		
Dwight A. Tipton	10. FIELD OR WILDCAT NAME	
3. ADDRESS OF OPERATOR	Allison Penn	
P. O. Box 755, Hobbs, NM 88241 4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA	
below.)	Sec. 13 T8S R36E	
AT SURFACE: 554' FSL & 554' FEL of Sec. 13 AT TOP PROD. INTERVAL:	12. COUNTY OR PARISH	
AT TOP PROD. INTERVAL: AT TOTAL DEPTH:	Roosevelt	<u>NM</u>
	14. API NO.	
16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA	15. ELEVATIONS (SHOW DF, KDB, AND WD)	
SHOOT OR ACIDIZE	(NOTE: Report results of mu change on Form 9–	· ·
17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly stat including estimated date of starting any proposed work. If well is d measured and true vertical depths for all markers and zones pertiner It is proposed to plug and abandon as foll Spot 100' plug 4935- to 5035. Tag top of plug. Spot 100' plug 4100 to 4200. Perforate @ 2200 & squeeze with sufficient	lirectionally drilled, give sub nt to this work.)* .OWS:	ssurface locations and
come back to 2100. Spot 100' plug 360 to 460. <i>flug must b</i> Set 50' surface plug with regulation marke Mud between all plugs.	e in and behind . er	all caping
Subsurface Safety Valve: Manu. and Type	Set	t @ F1
18. I hereby certify that the foregoing is true and correct		
18. I hereby certify that the foregoing is true and correct SIGNED	DATE6/28,	/85
	fice use)	PROVED
SIGNED John Julka TITLE Agent	date DATE PETER	PROVED W. CHESTER L 51985

*See Instructions on Reverse Side

.

Now C.

BUREAU OF LAND MANAGEMENT ROSWELL RESOURCE AREA