

N. M. OIL CONS. COMMISSION
P. O. BOX 1980
HOBBS, NEW MEXICO 88240

Form 9-331
Dec. 1973

Form Approved.
Budget Bureau No. 42-R1424

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use Form 9-331-C for such proposals.)

1. oil ☒ gas ☐ other ☐
well well

2. NAME OF OPERATOR

SNB Operating Co.

3. ADDRESS OF OPERATOR

P.O. Box 543 Lovington N M 88260

4. LOCATION OF WELL (REPORT LOCATION CLEARLY. See space 17 below.)

AT SURFACE:

AT TOP PROD. INTERVAL:

AT TOTAL DEPTH:

16. CHECK APPROPRIATE BOX TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

REQUEST FOR APPROVAL TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF ☐

FRACTURE TREAT ☐

SHOOT OR ACIDIZE ☐

REPAIR WELL ☐

PULL OR ALTER CASING ☐

MULTIPLE COMPLETE ☐

CHANGE ZONES ☐

ABANDON* ☒

(other) ☐

5. LEASE

NM-051845

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

NM Federal

9. WELL NO.

1

10. FIELD OR WILDCAT NAME

Wildcat South Prairie WC

11. SEC., T., R., M., OR BLK. AND SURVEY OR
AR Sec. 20 T 8S R 36 E

12. COUNTY OR PARISH

13. STATE

Lea

N M

14. API NO.

15. ELEVATIONS (SHOW DF, KDB, AND WD)

4121 D F

(NOTE: Report results of multiple completion or zone change on Form 9-330.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

133/8-410'-400sxs

8/5/8-4335'-1978sxs

7" -9783'- 500 sxs

Perforations

8992'-9004'

1. CIBP @ 8900'-dump 35' cement on top
2. Circulate hole with 10# mud
3. cut and pull from freepoint all recoverable 7" casing
4. Spot 100' cement in and out of stub, 170' Tag plug
5. Spot 50 sxs cement @ 4385-4285' 4405'-4365' Tag plug
6. Cut and pull any 9 5/8 casing if free believe to be circulated
7. Spot 100' cement in and out of stub if pulled
8. Spot 85 sxs @ 460'-360'
9. Spot 10 sxs @ surface

Install Subsurface Safety Valve: Manu. and Type _____ Set @ _____ Ft.
dry hole marker

18. I hereby certify that the foregoing is true and correct

SIGNED

R. H. H.

TITLE

Agent

DATE

2-20-90

(This space for Federal or State office use)

APPROVED BY

TITLE

DATE

PETER W. CHESTER

CONDITIONS OF APPROVAL, IF ANY:

FEB 20 1990

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side

RECEIVED
FEB 23 9 01 AM '90
BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

RECEIVED

MAR 2 1990

OCD
HOBBS OFFICE