

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLI
(Other instructions
verse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

N.M. 058677-A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal N. M. "B" Fed

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

South Prairie Atoka Gas

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 21, T-8-S, R-36-E

12. COUNTY OR PARISH 13. STATE

Roosevelt

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS
(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. ☐ OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

Lone Star Producing Company

3. ADDRESS OF OPERATOR

Box 4815, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

660' North of South Line & 660' East of West Line of
Section 21, T-8-S, R-36-E, Roosevelt County, New Mexico

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4,115' Ground

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

PULL OR ALTER CASING

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

REPAIRING WELL

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

We desire your approval to plug and abandon Lone Star Producing Company's Federal N. M. "B" No. 1 Atoka Sand well. We plan to lay plug #1, 10 sacks cement from 12,038' up to 11,859' by displacement method; plug #2, 25 sacks from top of 3-1/2" O.D. liner at 9,476' up to 9,360'; plug #3, 25 sacks from 20' below where 7" O.D. casing is cut and pulled, 7,700', up to 7,620'; plug #4, 25 sacks from 5,500' up to 5,400'; plug #5, 25 sacks from 4,350' up to 4,300'; plug #6, 10 sacks in top of 9-5/8" O.D. protective casing; weld cap on top of 9-5/8" O.D.; install 4-1/2" O.D. well marker 4' 6" above ground level; clean location of debris and fill pits.

Note: The 13-3/8" O.D. casing, 9-5/8" O.D. protective casing and 3-1/2" O.D. liner will be left in hole. Hole will be filled with mud.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE Dist. Prod. Supt.

DATE February 2, 1966


(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side



Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.