

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE\*  
(Other instructions  
reverse side)Form approved.  
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

29-073669

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

LONE STAR FEDERAL

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

SOUTH PRAIRE WOLFCAMP

11. SEC., T., R., M., OR B&M, AND  
SURVEY OF AREA

SEC 20-8S.-36E.

12. COUNTY OR PARISH 13. STATE

ROOSEVELT NEW MEXICO

## SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT—" for such proposals.)OIL ☒ GAS ☐  
WELL ☒ WELL ☐ OTHER ☐

2. NAME OF OPERATOR

CARROLL H. NEELY

3. ADDRESS OF OPERATOR

Box 912 LOVINGTON, NEW MEXICO 88260

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)

At surface

660' FROM NORTH LINE AND 660' FROM EAST LINE  
SEC. 20-8S.-36E.

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

KB 4134

16.

## Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

## NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF ☐FRACTURE TREAT ☐SHOOT OR ACIDIZE ☐REPAIR WELL ☐(Other) ☐PULL OR ALTER CASING ☐MULTIPLE COMPLETE ☐ABANDON\* ☐CHANGE PLANS ☐

## SUBSEQUENT REPORT OF:

WATER SHUT-OFF ☐FRACTURE TREATMENT ☐SHOOTING OR ACIDIZING ☐(Other) ☒ PLUG BACKREPAIRING WELL ☐ALTERING CASING ☐ABANDONMENT\* ☐(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any  
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-  
nent to this work.)\*

## PROCEDURE AND RESULTS OF PLUG BACK TO WOLFCAMP -

1. SET RBP @ 9084 AND PERFORATED WOLFCAMP SECTION FROM 8960 - 8986
2. ACIDIZED PERFORATIONS WITH 1000 GALS 15% MCA ACID - AT 1 BPM @ 3200# -
3. SWAB WELL AND WAS NO SHOW OF OIL OR GAS
4. ACIDIZED PRFORATIONS WITH 3500 GALS 15% N E ACID AT 5B PM @ 4800#
5. SWAB ACID WATER BACK AND RECOVERED 50 BHPD WITH NO SHOW OF OIL OR GAS

18. I hereby certify that the foregoing is true and correct

SIGNED

*Carroll H. Neely*

TITLE

OWNER

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

ACCEPTED FOR RECORD

DEC 5 1977

U. S. GEOLOGICAL SURVEY  
HOBBS, NEW MEXICO

DATE

12-2-77

DATE

\*See Instructions on Reverse Side