

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

SUBMIT IN TRIPLICATE
(Other instructions on
reverse side)

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

02875

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

ANDERSON

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

ALLISON-PENN

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

J-31-B-37

12. COUNTY OR PARISH

ROOSEVELT

13. STATE

NEW MEXICO

1.

OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. NAME OF OPERATOR

PETROBRAS, INC.

3. ADDRESS OF OPERATOR

4219 SIGMA ROAD

DALLAS, TEXAS 75240

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)

At surface

1980' N. OF S. LINE AND 1980' W. OF E. LINE OF
SEC. 31

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

KB-4050 - GL 4036

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☒
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

SET RETAINER PLUG @ 6420' INSIDE 4-1/2" OD CASING AND PUMP 100 SACK CEMENT PLUG BELOW
SET 130' PLUG ON TOP RETAINER @ 6420' TO 6290' WITH 14 SACKS CEMENT
SET 335' PLUG @ 5600' TO 5265' WITH 25 SACKS CEMENT
SHOT 4-1/2" OD CASING @ 4009' CAME LOOSE @ 4250' (7 JNTS. BELOW SHOT)
SET 400' PLUG @ 4250' TO 3850' WITH 100 SACKS CEMENT
SET 175' PLUG @ 2200' TO 2025' INSIDE 7-5/8" OD CASING WITH 35 SACKS CEMENT
SET 250' PLUG @ 462' TO 212' INSIDE 7-5/8" OD CASING WITH 50 SACKS CEMENT
SET 40' PLUG @ 40' TO TOP WITH 10 SACKS CEMENT
~~WELDED STEEL PLATE IN TOP OF CASING~~ J. V.
SET DRY HOLE MONUMENT
CLEAN UP OF LOCATION AS PER REQUIREMENTS
PLUGGING OPERATION COMPLETED JUNE 1, 1976

18. I hereby certify that the foregoing is true and correct

SIGNED Sammy J. Wilson

TITLE AGENT

DATE JUNE 10, 1976

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

APPROVED

JAN 25 1977

ARTHUR R. BROWN
DISTRICT ENGINEER

*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

RECEIVED

JUN 1 1977

OIL & GAS ADMINISTRATION

DOBB, R. M.

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPL
(Other instructions
verse side)3*
re-Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

02875

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

ANDERSON

9. WELL NO.

5

10. FIELD AND POOL, OR WILDCAT

ALLISON-PENN

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

J-31-8-37

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

KB-4050 - GL 4036

12. COUNTY OR PARISH

13. STATE

ROOSEVELT

NEW MEXICO

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☒
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐

REPAIRING WELL

☐
☐
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other)

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

THIS WELL IS DEPLETED AND WE PROPOSE TO PLUG AND ABANDON
AS FOLLOWS:

SET RETAINER AT 6420' INSIDE 4-1/2 AND PUMP 100 SACKS CEMENT
SET 100' PLUG ON TOP OF RETAINER INSIDE OF 4-1/2
SET 100' PLUG AT GLORIETTA 5500' TO 5600', 25 SACKS INSIDE PIPE OR 35
SACKS OUTSIDE
SET 100' PLUG AT STUB OF 4-1/2, 35 SACKS
SET 100' PLUG AT 4150' TO 4250, 35 SACKS IN AND OUT OF INTERMEDIATE
SET 100' PLUG AT 2100' TO 2200', 35 SACKS INSIDE 7-5/8
SET 100' PLUG AT STUB OF 7-5/8, 50 SACKS IF CAN PULL
SET 100' PLUG AT 362' TO 462', 50 SACKS IN & OUT OF SURFACE
PUT 10 SACKS IN TOP
PUT UP DRY HOLE MARKER
HOLE WILL BE FOLLED WITH MUD BETWEEN PLUGS
CASING COLLAPSED AND TUBING CUT OFF AT # 6421'

18. I hereby certify that the foregoing is true and correct

SIGNED

James M. Abbott

TITLE

Agent

DATE


4-29-76

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE



*See Instructions on Reverse Side

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.