

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O. C. C.
NEW MEXICO OIL CONSERVATION COMMISSION
DEC 29 11 49 PM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Marathon Oil Company	8. Farm or Lease Name W. A. Mauvin Est.
3. Address of Operator P. O. Box 220, Hobbs, New Mexico	9. Well No. 2
4. Location of Well UNIT LETTER <u>N</u> <u>660</u> FEET FROM THE <u>South</u> LINE AND <u>1980</u> FEET FROM THE <u>West</u> LINE, SECTION <u>18</u> TOWNSHIP <u>8S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat Allison-Penn

15. Elevation (Show whether DF, RT, GR, etc.) DF 4063'	12. County Roosevelt
---	-------------------------

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Set a 40 sack cement plug at 7700' to cover all perforations. Cut 7" casing off at 4490'. Placed a 20 sack cement plug in and out of cut off 7" casing. Placed a 40 sack cement plug across the 9-5/8" casing shoe at 4220'. Placed a 10 sack cement plug in the 9-5/8" casing at the surface. The hole was filled with mud. A steel marker was installed per NMOCC specifications. Well plugged and abandoned 12-15-66.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.		
SIGNED <u>John W. Rung</u>	TITLE <u>Area Supt.</u>	DATE <u>12-27-66</u>
APPROVED BY <u>John W. Rung</u>	TITLE _____	DATE _____
CONDITIONS OF APPROVAL, IF ANY:		