

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEY

P. O. BOX 1980

ROSWELL, NEW MEXICO 88240

Form approved.
Budget Bureau No. 42-R1424.

5. LEASE DESIGNATION AND SERIAL NO.

NM-58537

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Irex Federal

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

Allison Penn

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 20, T-8-S, R-37-E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4051' DF

12. COUNTY OR PARISH

Roosevelt

13. STATE

N.M.

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

☐
☐
☐
☐

PULL OR ALTER CASING

☐
☐
☐
☐

FRACTURE TREAT

MULTIPLE COMPLETE

SHOOT OR ACIDIZE

ABANDON*

REPAIR WELL

CHANGE PLANS

(Other)

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

☐
☐
☐
☐

REPAIRING WELL

☐
☐
☐
☐

FRACTURE TREATMENT

ALTERING CASING

SHOOTING OR ACIDIZING

ABANDONMENT*

(Other) Re-Entry

☒(Note: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

5-17-88 Ran 4 3/4" bit back into 5 1/2" casing and tagged up at 5748' depth. Pulled out of hole with bit Rigged up McCullough. Ran 3-arm caliper in hole. Could not get below 5594' depth. Tools were not working. Rigged down McCullough. Picked up mule shoed sub and Baker Model "R" packer and tripped in hole. Worked mule shoed joint and packer through bad spot in casing at 5748'. Lowered packer to 5934' depth. Could not get torque to packer sufficient to get packer in setting position. Pulled out of hole. Left packer and 5 joints of 2 7/8" tubing above packer and approximately 15' piece of 2 7/8" in hole. Shut down for night.

5-18-88 Picked up 4 1/2" OD lead impression block and tripped in hole. Tagged up at 5666'. Set seven points weight down on block. Pulled out of hole with impression block. No distinguishable marks on bottom. Had small indentations as from formation material. Picked up 4 5/8" bit and tripped in hole. Tagged up at 5666' depth. Started washing down and rotating. Recovered large amount of formation material. Washed to 5743'. Started recovering very heavy mud and formation material. Well did not clean up but could not make further progress. Pulled 10 stands of tubing. Shut down for night.

18. I hereby certify that the foregoing is true and correct

SIGNED

Wm. B. Grosbeck

TITLE

District Engineer

DATE 5-26-88

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

ACCEPTED FOR RECORD
PETER W. CHESTER
DATE

JUN 15 1988

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side

Irex Federal No. 1

5-19-88

Laid down all tubing. Removed BOP. Installed tubing head and head flange and closed in well. Fenced mud pit and covered cellar. Temporarily abandoned well.