

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State ☐ Fee ☒

5. State Oil & Gas Lease No.

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Unit Agreement Name
2. Name of Operator Tom L. Ingram	8. Farm or Lease Name Hayes
3. Address of Operator POB 1757, Roswell, New Mexico 88201	9. Well No. 1
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>29</u> TOWNSHIP <u>8S</u> RANGE <u>37E</u> NMPM.	10. Field and Pool, or Wildcat Allison Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4039 GL	12. County Roosevelt

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work, SEE RULE 1103.

January 11, 1975 thru January 20, 1975:

Set C.B.P @ 9400'. Put 35' of cement on top. Cut 5½" casing @ 4906 and pulled. Put 100' plug @ 4856 - 4956. Put 100' plug @ 4170-4270. (Base of 8-5/8") Put 100' plug at 2250-2350 (Top Salt). Put 10 sack plug @ surface with marker. Mud laden brine used between all plugs.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Tom L. Ingram

TITLE Operator

DATE 2/5/75

APPROVED BY John W. Rungen

TITLE Geologist

DATE JUL 9 1990

CONDITIONS OF APPROVAL, IF ANY: