

UNITED STATES  
DEPARTMENT OF THE INTERIOR  
GEOLOGICAL SURVEY

SUBMIT IN TRIP DATE\*  
(Other instructions on re-  
verse side)

Form approved.  
Budget Bureau No. 42-R1424.  
5. LEASE DESIGNATION AND SERIAL NO.

**MM-02875**

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

**Anderson**

9. WELL NO.

**4**

10. FIELD AND POOL, OR WILDCAT

**Allison-Penn**

11. SEC., T., R., M., OR BLK. AND  
SURVEY OR AREA

**Sec. 29-65-37E**

12. COUNTY OR PARISH 13. STATE

**Roosevelt**

**New Mexico**

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.  
Use "APPLICATION FOR PERMIT" for such proposals.)

1.

OIL WELL ☒ GAS WELL ☐ OTHER

**FEB 1 11 53 AM '66**

2. NAME OF OPERATOR

**Tom L. Ingram**

3. ADDRESS OF OPERATOR

**P. O. Box 1757 - Roswell, New Mexico**

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\*  
See also space 17 below.)  
At surface

**660' FSL & 660' FEL**

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

**4037 S.L.**

16.

**Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data**

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON\*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT\*

(NOTE: Report results of multiple completion on Well  
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

**Unable to pull tubing. Cut tubing at 9475'. Set 16-sack cement plug at top of tubing stub. Cut casing at 4800' and pulled from surface to 4800'. Set 40-sack cement plug in and out of 7-5/8' casing. Set plug at top and marker. Mud was used between plugs. Location cleared and ready for inspection.**

18. I hereby certify that the foregoing is true and correct

SIGNED

**Martha J. West**

TITLE

**Clerk**

DATE

**January 24, 1966**

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

DATE

**JAN 26 1966**

\*See Instructions on Reverse Side

ACTING DISTRICT ENGINEER