

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT IN TRIPPLICATE
(Other instructions on re-
verse side)Form approved
Budget Bureau No. 42-R1424

5. LEASE DESIGNATION AND SERIAL NO.

NM-05065

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Federal "H"

8. FARM OR LEASE NAME

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

South Prairie

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

Sec. 17-T8S-R36E NMPM

12. COUNTY OR PARISH

13. STATE

Roosevelt New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)1. OIL ☒ GAS ☐
WELL WELL OTHER

2. NAME OF OPERATOR

Joseph I. O'Neill, Jr.

3. ADDRESS OF OPERATOR

410 West Ohio, Midland, Texas 79701

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.
See also space 17 below.)
At surface

1874' FSL and 554' FEL of Section 17

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4124' DF, 4114' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

*

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(Note: Report results of multiple completion on Well
Completion or Completion Report and Log form.)17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any
proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones perti-
nent to this work.)

San Andres tested under October 20, 1969 approval.

Perforated single holes at 4982, 85, 86, 92, 95, 98, 5002, 05, 08, 5128, 32, 36,
40, 45, 50, 53.

All San Andres zones produced saltwater with sh w of oil.

PROPOSED ABANDONMENT PROGRAM

Set 40 cu ft cement on top of CIBP set at 5310'.

Cement plug will be from 5310 to 4832'.

Cut 4 1/2" csg at top of outside cement 4450' and recover same.

Set 35 cu ft plug at 7 5/8", 3265-3140'.

Cut 7 5/8" at top of outside cement at 3140' or at point csg is free and recover same.

Set 60 cu ft plug 475-375'.

Set 10 cu ft plug in top, cover 10 3/4" csg and set steel plate and mount marker as
required by New Mexico Oil Conservation Commission rules.

Proposed work to commence immediately upon approval.

18. I hereby certify that the foregoing is true and correct

SIGNED

E. T. Anderson

(This space for Federal or State office use)

TITLE

Drig & Prod Supt.

TITLE

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

Amendment: Set additional

