

Form 3160-5
(June 1990)

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
Budget Bureau No. 1004-0135
Expires: March 31, 1993

SUNDRY NOTICES AND REPORTS ON WELLS

Do not use this form for proposals to drill or to deepen or reentry to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.

SUBMIT IN TRIPLICATE

1. Type of Well

☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator

O'Neill Properties, Ltd.

3. Address and Telephone No.

P. O. Box 2840, Midland, Texas 79702

915/683-2771

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)

Unit D, 660' FNL & 510' FWL, Sec. 34-8S-37E

5. Lease Designation and Serial No.

LC 068401

6. If Indian, Allottee or Tribe Name

7. If Unit or CA, Agreement Designation

8. Well Name and No.

Federal "K" No. 1

9. API Well No.

10. Field and Pool, or Exploratory Area

Allison (Penn)

11. County or Parish, State

Roosevelt

12. CHECK APPROPRIATE BOX(s) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION

☐ Notice of Intent

☒ Subsequent Report

☒ Final Abandonment Notice

TYPE OF ACTION

☒ Abandonment

☐ Recompletion

☐ Plugging Back

☐ Casing Repair

☐ Altering Casing

☐ Other

☐ Change of Plans

☐ New Construction

☐ Non-Routine Fracturing

☐ Water Shut-Off

☐ Conversion to Injection

☐ Dispose Water

(Note: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

13. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Well was permanently abandoned 12-15-93 by Kaiser-Francis Oil Company as follows:

1. MIRU cementers. Spot 60 sxs "H" plug 8068' - 7515'. Circ hole up to 5500' w/10# brine gel.
2. RU perforators, perf 4 holes @ 5500'. POH, load csg, pump into perfs @ 3 BPM @ 1000#.
3. TIH w/5 1/2" cmt retainer on 2 3/8" tbg., set @ 5340', pmp dwn tbg w/50 sxs "H".
4. POOH, left 30 sxs cmt on top retainer. Circ hole to surface w/10# brine gel.
5. GIH w/perf, shoot 4 holes @ 4280', POH, close BOP, pmp thru squeeze holes @ 4 BPM @ 250#. Set 5 1/2" cement retainer @ 4110', squeeze 50 sxs "H" @ 2 1/2 BPM @ 500#. Est. top @ 4132'.
6. GIH w/perf. shoot 4 holes @ 450'; POH, TIH w/5 1/2" cement retainer, set @ 297', pmp 50 sxs "H" @ 2 BPM @ 250#. POOH, left 30' cmt on top, had good circ out 5 1/2" - 8 5/8" annulus & out 8 5/8" - 13 3/8" annulus. Est. top @ 301'.
7. ND BOP, spot 15 sxs "H" 62' to surface. Cut off csg, install DH marker.
8. The surface restoration is complete and ready for inspection.

14. I hereby certify that the foregoing is true and correct

Signed [Signature]

Title Petroleum Engineer

Date 3-17-94

(This space for Federal or State office use)

Approved by [Signature]

Title Supervisor, Lands & Minerals

Date 5/18/94

Conditions of approval, if any:

Title 18 U.S.C. Section 1001, makes it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

*See Instruction on Reverse Side

RECEIVED

MAY 11 1994

U.S. AIR FORCE
OFFICE