

UNITED STATES DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
HOBBS, NEW MEXICO 88240
1980
SUBMIT IN TRIPlicate
(Other Instructions on Form 100-5)

Form approved.
Budget Bureau No. 1004 0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. UNIT AGREEMENT NAME
2. NAME OF OPERATOR Breck Operating Corp.	8. FARM OR LEASE NAME Bate Federal
3. ADDRESS OF OPERATOR P. O. Box 911, Breckenridge, Texas 76024	9. WELL NO. 2
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements. See also space 17 below.) At surface Unit letter F, 1980' FNL, 1980' FWL, Section 22, T-8-S, R-36-E.	10. FIELD AND POOL, OR WILDCAT S. Prairie/Cisco
14. PERMIT NO.	11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA Sec 22, T-8-S, R-36-E
15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4094' DF	12. COUNTY OR PARISH Roosevelt
	13. STATE N.M.

16 Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF <input type="checkbox"/>	PULL OR ALTER CASING <input type="checkbox"/>	WATER SHUT-OFF <input type="checkbox"/>	REPAIRING WELL <input type="checkbox"/>
FRACTURE TREAT <input type="checkbox"/>	MULTIPLE COMPLETION <input type="checkbox"/>	FRACTURE TREATMENT <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
SHOOT OR ACIDIZE <input type="checkbox"/>	ABANDON* <input checked="" type="checkbox"/>	SHOOTING OR ACIDIZING <input type="checkbox"/>	ABANDONMENT* <input type="checkbox"/>
REPAIR WELL <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	(Other) <input type="checkbox"/>	

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. (a) PLUG PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)
This well is no longer of any value to our company. A CIBP was placed in this well at 4710' on 05/24/82. The plug was set to allow testing of the integrity of the casing. Mr. Jim Graham, U.S. Dept. of Interior, Mineral Management Service in Hobbs, N. M. witnessed the test. This was the last work done to this well. The following is our recommendation for plugging and abandoning this well:

1. Place 5 sxs of cement on the existing CIBP. Applied through tubing.
2. Perforate 4-1/2" casing at 4100'. Squeeze 20 sxs of cement between 4-1/2" & 7-5/8" casing. Leave 10 sxs in 4-1/2" casing. Plug top - 3970'. Plug bottom - 4100'. To be applied through tubing & packer.
- * 3. Place 10 sxs of cement from 3'-53' in 4-1/2" casing. Use 1" pipe to place 10 sxs between the 4-1/2" & 7-5/8" casing. Also, place 10 sxs between 7-5/8" & 10-3/4" casing.

All intervals between plugs to filled with 9.5#/gal mud.

- * Additional plugs needed whether casing pulled or not.
1. 100' cmt. plug 2850'-2750' (in 4 1/2" casing and both annuli if casing not pulled).
2. 100' cmt. plug 341'-241' (same as above). Tag plug.
3. 2 1/2" 4 1/2" casing pulled spot 100' cmt. plugs across steel.

18. I hereby certify that the foregoing is true and correct

SIGNED Daniel D. Wilson TITLE Production Engineer
(This space for Federal or State office use)

APPROVED BY _____ TITLE _____
CONDITIONS OF APPROVAL, IF ANY: *

APPROVED
PETER W. CHESTER

MAY 1 1985

BUREAU OF LAND MANAGEMENT
ROSWELL RESOURCE AREA

*See Instructions on Reverse Side

RECEIVED

MAY 6 1985

U.S. DEPT. OF JUSTICE
FEDERAL BUREAU OF INVESTIGATION