

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT "TRIP" DATE
(Other in stior re-
verse side)Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM-044216-C

6. INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME
Federal

9. WELL NO.

10. FIELD AND POOL, OR WILDCAT

East Bluff San Andres

11. SEC., T., R., M., OR B.L. AND
SURVEY OR AREA

24 - 85 - 37E

12. COUNTY OR PARISH

13. STATE

Roosevelt

New Mexico

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT" for such proposals.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐	
2. NAME OF OPERATOR TOM L. INGRAM	
3. ADDRESS OF OPERATOR P. O. Box 1757, Roswell, New Mexico 88201	
4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.* See also space 17 below.) At surface 660 FNL & 1980 FNL of Section	
14. PERMIT NO.	15. ELEVATIONS (Show whether DF, RT, GR, etc.) 4003 DF

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log Form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

3/9/69 Squeezed perforations from 4746-4766 with 100 sx. of Incon cement. Maximum squeeze pressure 2500 psi.

3/10/69 WOC 48 hours. Tested to 1000 psi for 30 minutes. Held okay.

3/11/69 Drilled cement to 4814. Pressured to 2500 psi for 30 minutes. Held okay.

3/12/69 Perforated with one spf 4745-4754. Acidized with 500 gals. HCA. Formation took fluid at 700 psi. Treated at 5½ bbls. of fluid per minute at 2700 psi ISDP 1200. On vacuum in 2½ minutes.

3/13/69 Swabbed oil cut water.

3/14/69 Swabbed oil cut water. Static fluid level 3000' from surface while swabbing; 2000' from surface while shut in.

3/15, 16 & 17/69 Shut down because of snow.

3/18/69 Ran Tracer Survey and found fluid going out perforations and down into P₃. Prep to resqueeze.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Operator

DATE March 18, 1969

(This space for Federal or State office use)

APPROVED BY

TITLE

APPROVED

DATE

CONDITIONS OF APPROVAL, IF ANY:

MAR 19 1969

*See Instructions on Reverse Side L. GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations, and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.

UNITED STATES
DEPARTMENT OF THE INTERIOR
GEOLOGICAL SURVEYSUBMIT (Other 1.
verse side) TRIP DATE re-Form approved.
Budget Bureau No. 42-R1424.
5. LEASE DESIGNATION AND SERIAL NO.

NM-044216-C

6. INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

8. FARM OR LEASE NAME

Federal "E"

9. WELL NO.

1

10. FIELD AND POOL, OR WILDCAT

East District San Andres

11. SEC., T., R., M., OR BLK. AND
SURVEY OR AREA

24 - 85 - 37E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4003 DF

12. COUNTY OR PARISH

Roosevelt

13. STATE

New Mexico

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other)

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well
Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

Respudded 2/24/68. Cleaned to old total depth of 4830'. Drilled to 4834'. Ran 4837' of 4 1/2" 10 1/2" J-55 casing to TD. Cemented with 200 sx 50-50 Pemmix plus 2% gel and 8# salt per sack and 50 sacks of neat. Plugged down @ 4:30 P.M. 2/26/68. WOC 48 hours. Tested casing and shoe to 1000 psi for 30 minutes. Held okay. Ran Tie-in Log. Perforated with 1 spf @ 4746, 4747, 4748, 4750, 4751, 4753, 4756, 4758 and 4768. Acidized above perforations with 4500 gallons of DS-30. Spabbling oil, gas and water.

18. I hereby certify that the foregoing is true and correct

SIGNED

TITLE

Operator

DATE March 6, 1968

(This space for Federal or State office use)

APPROVED BY

CONDITIONS OF APPROVAL, IF ANY:

TITLE

APPROVED

DATE

MAR 10 1968

*See Instructions on Reverse Side

J. L. GORDON
ACTING DISTRICT ENGINEER

Instructions

General: This form is designed for submitting proposals to perform certain well operations, and reports of such operations when completed, as indicated, on Federal and Indian lands pursuant to applicable Federal law and regulations; and, if approved or accepted by any State, on all lands in such State, pursuant to applicable State law and regulations. Any necessary special instructions concerning the use of this form and the number of copies to be submitted, particularly with regard to local, area, or regional procedures and practices, either are shown below or will be issued by, or may be obtained from, the local Federal and/or State office.

Item 4: If there are no applicable State requirements, locations on Federal or Indian land should be described in accordance with Federal requirements. Consult local State or Federal office for specific instructions.

Item 17: Proposals to abandon a well and subsequent reports of abandonment should include such special information as is required by local Federal and/or State offices. In addition, such proposals and reports should include reasons for the abandonment; data on any former or present productive zones, or other zones with present significant fluid contents not sealed off by cement or otherwise; depths (top and bottom) and method of placement of cement plugs; mud or other material placed below, between and above plugs; amount, size, method of parting of any casing, liner or tubing pulled and the depth to top of any left in the hole; method of closing top of well; and date well site conditioned for final inspection looking to approval of the abandonment.