

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

MAY 8 11 11 AM '69

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No. -
7. Unit Agreement Name -
8. Farm or Lease Name Matthews
9. Well No. 1
10. Field and Pool, or Wildcat Allison (Penn)
12. County Roosevelt

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER- 2. Name of Operator Shell Oil Company 3. Address of Operator P. O. Box 1509, Midland, Texas 79701 4. Location of Well UNIT LETTER H, 1980 FEET FROM THE North LINE AND 660 FEET FROM THE East LINE, SECTION 19 TOWNSHIP 8-S RANGE 37-E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4050' DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

April 30 thru May 1, 1969

1. Rigged up casing pullers. Spotted 25 sacks plug across casing perfs. WOC 24 hours, did not hold.
2. Spotted 40 sacks across perfs, WOC 24 hours, plug, did not hold.
3. Spotted 50 sacks across perfs, WOC, plug held. Displaced hole with mud.
4. Pulled and laid down tubing.
5. Pulled casing, spotted 10 sacks at surface.
6. Cut off wellhead and erected prescribed marker.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED N.W. Harrison TITLE Staff Operations Engineer DATE 5-7-69

APPROVED BY John W. Ryan TITLE Staff Operations Engineer DATE 5-7-69

CONDITIONS OF APPROVAL, IF ANY: