

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

JUN 13 9 19 AM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. E-8876
7. Unit Agreement Name -
8. Farm or Lease Name New Mexico State "AA"
9. Well No. 2
10. Field and Pool, or Wildcat Allison Penn
12. County Roosevelt

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>
2. Name of Operator Sunray DX Oil Company
3. Address of Operator P. O. Box 1416, Roswell, New Mexico
4. Location of Well UNIT LETTER B , 660 FEET FROM THE North LINE AND 1980 FEET FROM THE East LINE, SECTION 36 , TOWNSHIP 8S , RANGE 36E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4074 DF

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

P&A as follows:

1. Load hole with mud. Place 25 sx cmt plug over parfs (9651-9673) from BPTD 9703 to 9400'.
2. Pulled 4192' of 4 1/2" casing.
3. Placed 50 sx plug from 4245'-4100'.
4. Placed 10 sx cmt top cap.
5. Cut off casing at ground level, installed dry hole marker and cleared junk from location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. Brawley **B. Brawley** TITLE District Engineer DATE June 10, 1966

APPROVED BY Leslie M. Stewart TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: