

**N. M. OIL CONS. COMMISSION**  
**UNITED STATES DEPARTMENT OF THE INTERIOR**  
**BUREAU OF LAND MANAGEMENT**

BLM Roswell District  
Modified Form No.  
ND60-3160-4

5. LEASE DESIGNATION AND SERIAL NO.

LC-062178

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Milnesand Unit

8. FARM OR LEASE NAME

9. WELL NO.

53

10. FIELD AND POOL, OR WILDCAT

Milnesand (San Andres)

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 13, T-8S, R-34E

12. COUNTY OR PARISH 13. STATE

Roosevelt New Mexico

**SUNDRY NOTICES AND REPORTS ON WELLS**

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir. Use "APPLICATION FOR PERMIT" for such proposals.)

1.  OIL WELL  GAS WELL  OTHER

2. NAME OF OPERATOR: Breck Operating Corp. 3a. Area Code & Phone No.: (817) 559-3355

3. ADDRESS OF OPERATOR: P.O. Box 911, Breckenridge, Texas 76024

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.\* See also space 17 below.)  
At surface  
Unit Letter "E"; 1980' FNL & 660' FWL

14. PERMIT NO. 15. ELEVATIONS (Show whether DF, RT, CR, etc.)  
4266' (DF)

**Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data**

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

TEST WATER SHUT-OFF   
 FRACTURE TREAT   
 SHOOT OR ACIDIZE   
 REPAIR WELL   
 (Other)

PULL OR ALTER CASING   
 MULTIPLE COMPLETE   
 ABANDON\*   
 CHANGE PLANS

WATER SHUT-OFF   
 FRACTURE TREATMENT   
 SHOOTING OR ACIDIZING   
 (Other)

REPAIRING WELL   
 ALTERING CASING   
 ABANDONMENT\*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)\*

COMPLETED OPERATIONS

- 4/12/90: MIRU. POOH & LD 152-5/8" rods. Install BOP. POOH w/149 jts 2-3/8" tbg. Attempt to RIH w/4-1/2" CIBP-csg parted @ surface. Dug out WH. RIH w/CIBP on WL. Set @ 4475'. POOH w/WL. SDFN.
- 4/13/90: Welded 4-1/2" nipple onto top of parted csg. Dump 3 sx cmt on top of CIBP. Stretch indicated csg free @ 4000'. Shoot csg @ 3980'. Csg not free. SDFWE.
- 4/16/90: RIH w/tbg to 3980'. Pmp 35 sx cmt plug. POOH w/tbg. RIH w/WL to shoot csg. WL parted. Fished WL w/tbg. Circ hole w/brine water. RIH w/WL & shoot csg @ 3700'. Csg free. POOH & LD 24 jts 4-1/2" csg. SDFN. BLM approved altered plugging operations.
- 4/17/90: POOH & LD 101 jts 4-1/2" csg. RIH w/tbg to 3700'. Pmp 35 sx cmt plug. WOC 3 hrs. Tag top of cmt plug @ 3630'. Load hole w/salt gel mud. POOH w/tbg to 372'. Pmp 30 sx cmt plug. POOH w/tbg. Dump 15 sx surface plug. SDFN. BLM approved plugging operations.
- 4/18/90: Cut off WH. Remove anchors. Construct Dry-Hole marker. RDMO.

18. I hereby certify that the foregoing is true and correct

SIGNED Kevin G. Duncan  
 Kevin Duncan  
 (This space for Federal or State office use)

TITLE Petroleum Engineer

DATE 4/20/90

APPROVED BY \_\_\_\_\_  
 CONDITIONS OF APPROVAL, IF ANY: \_\_\_\_\_

TITLE \_\_\_\_\_

APPROVED  
 PETER W. CHESTER  
 MAY 23 1990  
 BUREAU OF LAND MANAGEMENT  
 ROSWELL RESOURCE AREA

BUREAU OF LAND MANAGEMENT  
 ROSWELL RESOURCE AREA  
 APR 23 1990  
 ROSWELL, NEW MEXICO

\*See Instructions on Reverse Side