			•
NO. OF COPIES RECEIVED			Form C-103
DISTRIBUTION			Supersedes Old C-102 and C-103
SANTA FE	NEW MEXICO OIL CONSE	RVATION COMMISSION	Effective 1-1-65
FILE			
U.S.G.S.			5a. Indicate Type of Lease
LAND OFFICE			State Fee X
OPERATOR			5. State Oil & Gas Lease No.

(DO NOT USE THIS FORM FOR T	DRY NOTICES AND REPORTS ON W proposals to dr: LL or to deepen or plug bac ation for permit -" (form C-101) for such	FELLS to a different reservoir. proposals.)	
1.			7. Unit Agreement Natus
OIL GAS WELL	OTHER-		Milnesand Waterflood
2. Name of Operator			8. Farm or Lease Name
UNION TEXAS PETROLEUM CORPORATION			Milnesand Unit
3. Address of Operator			9. Well No.
1300 Wilco Building, Midland, Texas 79701			513
4. Location of Well			10. Field and Pool, or Wildcat
Н	1980 FEET FROM THE North	660	Milnesand (San Andres)
UNIT LETTER	FEET FROM THE	LINE AND FEET FROM	
East LINE, SEC	24 TOWNSHIP 8-S	34-Е	
THELINE, SEC	TION TOWNSHIP	RANGE NMPM.	
mmmmmmm			
	15. Elevation (Show whether D	PF, RT, GR, etc.)	12. County
	15. Elevation (Show whether D 4242' DF	F, RT, GR, etc.)	12. County Roosevelt
	4242' DF		Roosevelt
Chec	4242' DF k Appropriate Box To Indicate Na	nture of Notice, Report or Ot	Roosevelt Aller Data
Chec	4242' DF	nture of Notice, Report or Ot	Roosevelt
	4242' DF k Appropriate Box To Indicate Na INTENTION TO:	nture of Notice, Report or Ot	Roosevelt Aller Data
	4242' DF k Appropriate Box To Indicate Na INTENTION TO:	ature of Notice, Report or Otl SUBSEQUEN	Roosevelt her Data report of:
Check NOTICE OF PERFORM REMEDIAL WORK	4242' DF k Appropriate Box To Indicate Na INTENTION TO:	REMEDIAL WORK	Roosevelt her Data report of: Altering casing
	4242' DF k Appropriate Box To Indicate Na INTENTION TO: PLUG AND ABANDON	REMEDIAL WORK	Roosevelt her Data report of: Altering casing
Check NOTICE OF PERFORM REMEDIAL WORK	4242' DF k Appropriate Box To Indicate Na INTENTION TO: PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK	Roosevelt her Data report of: Altering casing
Check NOTICE OF PERFORM REMEDIAL WORK	4242' DF k Appropriate Box To Indicate Na INTENTION TO: PLUG AND ABANDON CHANGE PLANS	REMEDIAL WORK	Roosevelt her Data r REPORT OF: Altering casing plug and abandonment

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of sturting any proposed work) SEE RULE 1103.

1. Pull 2 3/8" tubing, inspect and plastic coat internally.

- 2. Run plastic coated tubing w/Injection Packer set @ approximately 4500'.
- 3. Treat injection zone w/approximately 1000 Gal. clean sweep.
- 4. Place on water injection.

* Case No. 4140, Order No. R-3770 authorizes use of this well for water injection Well formerly designated as Sun DX - N. M. Federal "F" #13.

.

18. I hereby certify that the information above is true and complet.	e to the best of my knowledge and belief.
SIGNED Kumanny	TITLE District Oper. Supt. Western DATE July 19, 1971
APPROVED BY Kielis & Clamint	TITLE OTAS GER SPECTCH JUL 21 1971

CONDITIONS OF APPROVAL, IF ANY: