

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

H0245 OFFICE C. C. C.
 NEW MEXICO OIL CONSERVATION COMMISSION
 JAN 17 11 48 AM '67

Form C-103
 Supersedes Old
 C-102 and C-103
 Effective 1-1-65

5a. Indicate Type of Lease
State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
 USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Water Disposal Well	7. Unit Agreement Name -
2. Name of Operator Sunray DX Oil Company	8. Farm or Lease Name Nancy Watson
3. Address of Operator P. O. Box 1416 - Roswell, New Mexico	9. Well No. 2
4. Location of Well UNIT LETTER K , 1980 FEET FROM THE South LINE AND 660 FEET FROM THE West LINE, SECTION 31 TOWNSHIP 8-S RANGE 34-E N.M.P.M.	10. Field and Pool, or Wildcat Clr. San Andres
15. Elevation (Show whether DF, RT, GR, etc.) 4312 GR	12. County Roosevelt

16.

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
 TEMPORARILY ABANDON ☐
 PULL OR ALTER CASING ☐
 OTHER ☐

PLUG AND ABANDON ☐
 CHANGE PLANS ☐
 OTHER ☐

REMEDIAL WORK ☐
 COMMENCE DRILLING OPNS. ☐
 CASING TEST AND CEMENT JOB ☐
 OTHER ☐

ALTERING CASING ☐
 PLUG AND ABANDONMENT ☒
 OTHER ☐

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE: RULE 1103.

1. Commenced plugging procedures December 11, 1966.
2. Load hole with mud.
3. Spot 25 sx. cmt. plug across perms. (4622-4287).
4. Cut off 4 1/2 csg. @ 1770' & lay csg. down keeping hole loaded with mud.
5. Spot 25 sx. cmt. plug @ (1804-1641) in & out of 4 1/2 csg. stub.
6. Spot 25 sx. cmt. plug @ (462'-302') in & out of 8 5/8 surface csg.
7. Place 10 sx. cmt plug @ surface.
8. Install dryhole marker.
9. Remove surface equipment and clean location.
10. Job complete - December 14, 1966.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED B. F. Brawley TITLE District Engineer DATE 1-16-67

APPROVED BY [Signature] TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: