· ·		'			
NO. OF COPIES RECEIVED		000 0 0 0	Form C-103		
DISTRIBUTION		,	Supersedes Old C-102 and C-103		
SANTA FE	NEW MEXICO OIL CONSERVATION	COMMISSION	Effective 1-1-65		
FILE	JAN 13 11				
U.S.G.S.		5	a. Indicate Type of Lease		
LAND OFFICE			State X Fee		
OPERATOR		5	. State Oil & Gas Lease No. K 2734		
(DO NOT USE THIS FOR FOR	DRY NOTICES AND REPORTS ON WELLS proposals to drill or to deepen or plug back to a diffi cation for permit - (form C-101) for such proposals.)				
1. OIL X GAS WELL	OTHER-	7	'. Unit Agreement Name		
2. Name of Operator Non-Operator:			8. Farm or Lease Name		
Champlin Petroleum Company Warren American Oil Company			State 32-7-33		
3. Address of Operator		9	. Well No.		
P. O. Box 1797, Mi	land, Texas		2		
4. Location of Well		1	0. Field and Pool, or Wildcat		
UNIT LETTER	660 FEET FROM THE North LINE AND	660	Chaveroo-San Andres		
THE East Line, si	CTION 32 TOWNSHIP 7-8 RANGE	<u>33-E</u> NMPM.			
15. Elevation (Show whether DF, RT, GR, etc.)			2. County		
	4413' GR		Roosevelt ()////////		
^{16.} Chee	k Appropriate Box To Indicate Nature of N	otice, Report or Other	r Data		
	INTENTION TO:	SUBSEQUENT F			
PERFORM REMEDIAL WORK	PLUG AND ABANDON REMEDIAL W		ALTERING CASING		
TEMPORARILY ABANDON		RILLING OPNS.	PLUG AND ABANDONMENT		
PULL OR ALTER CASING	CHANGE PLANS CASING TEST	AND CEMENT JOB			
			L`_		
OTHER					

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well was acidized and never fraced and production had declined down below the daily allowable. On 1-8-66 Pulled rods and tubing out of hole. Reperforsted well 2 holes each @ 4245, 4252, 4261, 4268, & 4273. In hole with Halliburton RTTS Packer and bridge plug. Tested casing and casing was leaking, found hole in casing @ 1136'. Went ahead and acidized same perforations w/750 gal. of acid. Set a Halliburton frac liner from 1121' to 1149' and frac w/40,000 gal. of gel formation water & 40,000# sand. Pulled Halliburton frac liner out of hole and set 20' of Halliburton Stress Steel Liner with top from 1126' to 1146' to patch hole @1136'. Ran rods and tubing, put well back to pumping.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED 7/7 Parallen	H. N. Brown TITLE	District Superintendent	DATE	1-12-66
5				:
APPROVED BY	TITLE		DATE	<u></u>