STATE OF NEW MEXICO	
UIL CONSERVATION DIVISION	
DISTRIBUTION P. O. BOX 2088	Form C-103
SANTA FE SANTA FE, NEW MEXICO 87501	Revised 10-1-78
FILE	5a. Indicate Type of Lease
U.8.C.S.	State Fee X
LAND OFFICE OPERATOR	5. State Oil & Gas Lease No.
	91-011574
SUNDRY NOTICES AND REPORTS ON WELLS	<u> XIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIIII</u>
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C+101) FOR SUCH PROPOSALE.}	7. Unit Agreement Name
	Milnesand Waterflood
WELL WELL OTHER. WIW	8. Farm or Lease Hame
Breck Operating Corp.	Milnesand Unit
3. Address of Operator	9. Well No.
P.O. Box 911, Breckenridge, Texas 76024	136
4. Location of Well 1000 North 660	10. Field and Pool, or Wildcat
H 1980 North 660	Milnesand (San Andres)
East 7 8-S 35-E	
THERANGENMPN	• {////////////////////////////////////
; [] [] [] [] [] [] [] [] [] [] [] [] []	12. County
;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;;	Roosevelt
16. Check Appropriate Box To Indicate Nature of Notice, Report or O	ther Data
••••	IT REPORT OF:
	[ <b></b> ]
PERFORM REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON COMMENCE DRILLING OPHS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING	
OTHER	
	a estimated date of starting any proposed
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, includin work) SEE RULE 1903.	
The reason we plan to abandon this well is it is of no further use t	o the waterflood unit.
The reason we plan to abandon this well is it is of no intrinci use a The producing wells it once benefitted are all either plugged and ab	andoned or temporarily
abandoned.	
Well Record: 8-5/8" 24# J-55 casing set @ 413' in 11" hole w/200 sx regular cement.	
Cement circulated. $4-\frac{1}{2}$ " 9.5# J-55 casing set @ 4710' in 7-7/8" hole w/150 sx posmix & 200 sx	
$4-2^{-9}$ 9.5% J-55 casing set ( 4710 in 7-778 hore with 5 5k point a 200 cm neat cement. TOC 3735'.	
2-3/8" EUE 8 rd plastic coated tbg w/pkr set @ 4543'.	Injection interval:
4630-4669' TD: 4720' PBTD: 4680'	2
	•
Plugging procedure: Pump 19 sx from 4600-4500'.	
Pump 40 sx from 463-363' in & out $4-\frac{1}{2}$ " csg.	
Dump 10 sx surface plug. Cut the wellhead off 3' below surface & weld ca	ap on CSG.
9.5 lb/gal. mud will be placed below, between,	and above plugs.
The work should be completed and well site conditioned for final ins	spection by
February 28, 1987, or as soon as we have partner approval to do so.	
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.	
Keyin G. Duncan Him G. Dunian Petroleum Engineer	2-17-87
ORIGINAL SIGNED BY JERRY SEXTON	FER 2 3 1987
DISTRICT I SUPERVISOR	_ DATE A D LUT
CONDITIONS OF APPROVAL, IF ANY:	

-