

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resource Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. BOX 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec NM 87410

WELL API NO.

30-041-10057

5. Indicate Type of Lease

STATE ☐ FEE ☒

6. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH
PROPOSALS.)

1. Type of Well:

OIL GAS
WELL ☐ WELL ☐ OTHER INJECTION

2. Name of Operator

MAERSK ENERGY Inc.

3. Address of Operator

2424 Wilcrest, Suite 200, Houston, TX 77042-2753

8. Well No.

187

9. Pool name or Wildcat

Milnesand (San Andres)

4. Well Location

Unit Letter B : 660 Feet From The North Line and 1980 Feet From The East Line

NW NE Section 18 Township 8S Range 35E NMPM County Roosevelt

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4238.0'

11.

Check Appropriate Box to Indicate Nature of Notice, Report, Or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐
OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐ ALTERING CASING ☐
COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐
CASING TEST AND CEMENT JOB ☐
OTHER: CLEAN-OUT, REPERFORATE, AND STIMULATE ☒

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Work Described: Thru tubing clean-out, reperforating & stimulation of San Andres Injection Well

Work Commenced: 05/17/93

Work Completed: 05/20/93

Operations Detail:

- 1) Cleaned-out well to 4710' with coiled tubing.
- 2) Spot 220 gallons of S444 Calcium Sulfate Converter Chemical.
- 3) Perforate San Andres with 4 SPF from:
4575' - 4577'
4581' - 4602'
4615' - 4644'
4648' - 4658'
- 4) Acidize San Andres perms with 2500 gallons of 15% HCL acid.
- 5) Place well back in service.

Thereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE George Sheffer TITLE DRILLING MANAGER DATE May 28, 1993

TYPE OR PRINT NAME GEORGE SHEFFER TELEPHONE NO. 713/783-0376

(This Space for State Use) ORIGINAL SIGNED BY JERRY DIXON

APPROVED BY George Sheffer TITLE DRILLING MANAGER DATE JUN - 4 1993

CONDITIONS OF APPROVAL, IF ANY: