

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O.C.C.
NEW MEXICO OIL CONSERVATION COMMISSION

Mar 14 8 14 AM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Skelly
9. Well No. 1
10. Field and Pool, or Wildcat Undesignated
12. County Roosevelt

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole
2. Name of Operator FRANKLIN, ASTON & FAIR, INC.
3. Address of Operator P. O. Box 1090, Roswell, New Mexico
4. Location of Well UNIT LETTER A , 990 FEET FROM THE North LINE AND 990 FEET FROM THE East LINE, SECTION 29 TOWNSHIP 7South RANGE 35 East NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 4243' GR

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JQB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

March 10, 1966 re-entered well, ran tubing to bottom and spotted 15 sack cement plug over perforations at 4142 to 4275 feet. Pulled tubing, ran free point indicator, and shot 4 1/2" casing at 1285 feet. Spotted 25 sack cement plug at 1285 feet, 25 sack cement plug at 1100 feet at the top of the Salt, 25 sack cement plug at 265 feet at base of 8 5/8" surface casing, and a 10 sack cement plug with marker at surface. Cementing work was performed by the Halliburton Company.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED *Grant M. Smith* TITLE Geologist DATE March 11, 1966

APPROVED BY *Leslie A. Clements* TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

HOBBS OFFICE O.C.C.
NEW MEXICO OIL CONSERVATION COMMISSION

Mar 9 11 26 AM '66

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State ☐ Fee ☒

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Dry Hole	7. Unit Agreement Name
2. Name of Operator Franklin, Aston & Fair, Inc.	8. Farm or Lease Name Skelly
3. Address of Operator P. O. Box 1090, Roswell, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER A , 990 FEET FROM THE North LINE AND 990 FEET FROM THE East LINE, SECTION 29 TOWNSHIP 7 South RANGE 35 East NMPM.	10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 4243' GR	12. County Roosevelt

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Well spudded February 3, 1965. Set 265' 32#, J-55, 8 5/8" casing with 150 sacks cement circulated to surface. Drilled 7 5/8" hole to 4310' and set 4307' New 4 1/2", 9.5# casing with 250 sacks cement. Log shows top of cement at 3300'. Attempted completion through perforations at selected intervals from 4142 to 4275 feet but were unable to make a well. Well abandoned with 4 1/2" to 2 3/8" swedge nipple on casing and 2" orbit valve with 2" bull plug.

On March 10, 1966, plan to re-enter well, spot 15 sack cement plug over perforations with tubing, pull tubing, run free point indicator, shoot 4 1/2" casing at top of cement 3300' or at free point. Then spot 25 sack cement plug top 4 1/2" casing, 25 sack cement plug at 1100' at the top of the Salt, 25 sack plug at 265' at base of 8 5/8" surface casing, and 10 sack cement plug with marker at surface.

The above plugging program approved by telephone conversation with Mr. Ramey of the Oil Conservation Commission Office in Hobbs on March 8, 1966.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Grant M. Smith TITLE Geologist DATE March 8, 1966

APPROVED BY _____ TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: