

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT
N. M. OIL CONS. COMMISSION
P. O. BOX 1980
HOBBS, NEW MEXICO 88240

Form approved.
Budget Bureau No. 1004-0135
Expires August 31, 1985

SUNDRY NOTICES AND REPORTS ON WELLS

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.
Use "APPLICATION FOR PERMIT—" for such proposals.)

1. OIL WELL ☐ GAS WELL ☒ OTHER

2. NAME OF OPERATOR

MURPHY OPERATING CORPORATION

3. ADDRESS OF OPERATOR

P. O. Drawer 2648, Roswell, NM 88202-2648

4. LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*
See also space 17 below.)
At surface

Unit Ltr. P, 660' FSL & 660' FEL, Sec. 11, T8S, R37E

14. PERMIT NO.

15. ELEVATIONS (Show whether DF, RT, GR, etc.)

4020' GL

5. LEASE DESIGNATION AND SERIAL NO.

NM-041698A

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

7. UNIT AGREEMENT NAME

Bluitt San Andres Unit

8. FARM OR LEASE NAME

Bluitt San Andres Unit Sec. 11

9. WELL NO.

16

10. FIELD AND POOL, OR WILDCAT

Bluitt San Andres Assoc.

11. SEC., T., R., M., OR BLK. AND SURVEY OR AREA

Sec. 11, T8S, R37E

12. COUNTY OR PARISH 13. STATE

Roosevelt

New Mexico

16. Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

TEST WATER SHUT-OFF

FRACTURE TREAT

SHOOT OR ACIDIZE

REPAIR WELL

(Other)

PULL OR ALTER CASING

MULTIPLE COMPLETE

ABANDON*

CHANGE PLANS

SUBSEQUENT REPORT OF:

WATER SHUT-OFF

FRACTURE TREATMENT

SHOOTING OR ACIDIZING

(Other) shut-in well

REPAIRING WELL

ALTERING CASING

ABANDONMENT*

(NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.)

17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and zones pertinent to this work.)*

RU PU. TOH w/tubing & packer. PU new tubing, drill collars & bit & TIH to 4530'.
Drill out to 4618'. TOH and lay down tubing, drill collars and bit. Install wellhead
and shut in well.

18. I hereby certify that the foregoing is true and correct

SIGNED Melinda K. Hickman

TITLE Production Supervisor

DATE 9-26-88

(This space for Federal or State office use)

APPROVED BY

TITLE

CONDITIONS OF APPROVAL, IF ANY:

*See Instructions on Reverse Side

