

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

WELL API NO.
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No. K-1369
7. Lease Name or Unit Agreement Name Haley Chaveroo San Andres Sec. 33
8. Well No. 10
9. Pool name or Wildcat Chaveroo San Andres
10. Elevation (Show whether DF, RKB, RT, GR, etc.)

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Murphy Operating Corporation
3. Address of Operator P. O. Drawer 2648, Roswell, New Mexico 88202-2648
4. Well Location Unit Letter <u>J</u> : <u>1980</u> Feet From The <u>South</u> Line and <u>1980</u> Feet From The <u>East</u> Line Section <u>33</u> Township <u>7 South</u> Range <u>33 East</u> NMPM <u>Roosevelt</u> County

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: Convert to Injection Well <u>R-8760</u> <input checked="" type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

5-18-90 Rig up pulling unit. Pick up bulldog bailer. SLM in hole hit top of fill @ 4353'. Clean well out to 4402' (SLM) TOH with bailer lay down same SDFN.

5-19-90 Rig up wireline truck. Pick perf guns & TIH. Logger TD @ 4401'. Perforate (1JSPF) @ 4328', 4329.5', 4351.5', 4359', 4376', 4396' & 4399'. TOH & rig down wireline truck. Pick up packer & TIH as follows:

1 Halliburton R-4 packer	3.45
131 Jts. 2 3/8" 4.7# J-55 coated tb	4097.77
KBM correction	11.00
Pull 16 point set packer @	4112.22

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Lori Brown TITLE Production Supervisor DATE 6/11/90
TYPE OR PRINT NAME Lori Brown TELEPHONE NO. 505-623-7210

(This space for State Use)

ORIGINAL SIGNED BY JERRY SEXTON

APPROVED BY DISTRICT I SUPERVISOR TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY:

JUN 21 1990

R A N

E

RECEIVED

JUN 20 1990

303
HOBBS OFFICE

