

Submit 3 Copies
to Appropriate
District Office

State of New Mexico
Energy, Minerals and Natural Resources Department

Form C-103
Revised 1-1-89

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION
P.O. Box 2088
Santa Fe, New Mexico 87504-2088

WELL API NO.

5. Indicate Type of Lease

STATE ☐

FEE ☒

6. State Oil & Gas Lease No.
LC-062178

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT"
(FORM C-101) FOR SUCH PROPOSALS.)

7. Lease Name or Unit Agreement Name

Milnesand Unit

1. Type of Well:
OIL WELL ☒

GAS WELL ☐

OTHER

2. Name of Operator
Breck Operating Corp.

8. Well No.
111

3. Address of Operator
P.O. Box 911, Breckenridge, Texas 76024

9. Pool name or Wildcat
Milnesand (San Andres)

4. Well Location
Unit Letter G : 1980 Feet From The North Line and 1980 Feet From The East Line

Section 12

Township 8S

Range 34E

NMPM Roosevelt

County

10. Elevation (Show whether DF, RKB, RT, GR, etc.)

4253' (DF)

11.

Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐

PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐

CHANGE PLANS ☐

PULL OR ALTER CASING ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☐

ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐

PLUG AND ABANDONMENT ☒

CASING TEST AND CEMENT JOB ☐

OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

04/06/90: MIRU. POOH w/180 - 3/4" rods & pump. POOH w/148 jts. (4593') of 2-3/8" tubing. Install BOP. SDFWE.

04/09/90: RIH w/4-1/2" CIBP. Hit bridge @ 3850'. POOH. Call NMOCC - approved alternate procedure. RIH w/tbg. to 4550'. Pump 25 sx. cmt. plug. WOC 3 hrs. Tag top of plug @ 4300'. Perf 4-1/2" csg. @ 2050'. RIH w/tbg. to 2050'. Pump 35 sx. cmt. plug. POOH w/tbg. Cut 4-1/2" csg. @ 369'. SDFN. Plugging operations witnessed by NMOCC representative Jack Griffin.

04/10/90: POOH w/11 jts. (365') 4-1/2" csg. RIH w/tbg. to 419'. Pump 35 sx. cmt. plug. POOH w/tbg. Dump 10 sx. cmt. surface plug. CO WH. Install dry hole marker. Remove anchors. RDMO. Plugging operations witnessed by NMOCC representative Jack Griffin.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE

Kevin G. Duncan

TITLE Petroleum Engineer

DATE 04/16/90

TYPE OR PRINT NAME

TELEPHONE NO.

(This space for State Use)

OIL & GAS INSPECTOR

APPROVED BY

Jack Griffin

TITLE

DATE

CONDITIONS OF APPROVAL, IF ANY: