		-	
NO. OF COPIES RECEIVED			
<del></del>			Form C-103 Supersedes Old
DISTRIBUTION SANTA FE	NEW MEXICO OIL CHISERY	OFFICE O. C. C.	C-102 and C-103
FILE	NEW MEXICO OIL CONSERV	ATION COMMISSION	Effective 1-1-65
U.S.G.S.	lus 23	1 04 PM '67	5a. Indicate Type of Lease
LAND OFFICE	JUN L 3	• •	State X Fee
OPERATOR	•		5. State Oil & Gas Lease No.
			E-10047
SUNDRY NOTICES AND REPORTS ON WELLS			monimina
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  USE "APPLICATION FOR PERMIT —" (FORM C-101) FOR SUCH PROPOSALS.)			
1.			7. Unit Agreement Name
OIL X GAS OTHER.			
2. Name of Operator			8. Farm or Lease Name
Sunray DX 011 Company			New Mexico "AY" State
3. Address of Operator			9. Well No.
P. O. Box 1416, Roswell, New Mexico			2
4. Location of Well			10. Field and Pool, or Wildcat
UNIT LETTER A 990 FEET FROM THE NORTH LINE AND 990 FEET FROM			Todd San Andres
UNIT LETTER	FEET FROM THE	INE AND FEET FROM	million in the second
East	36 TOWNSHIP 78	35E	
THE LINE, SECTION	TOWNSHIP	RANGE JJE NMPM.	
	15. Elevation (Show whether DF,	RT, GR, etc.)	12. County
	4165 DF		Roosevelt
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:   SUBSEQUENT REPORT OF:			
SSESERGEN NEI ON OF			
PERFORM REMEDIAL WORK	PLUG AND ABANDON REN	MEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	<u> </u>	MMENCE DRILLING OPNS.	PLUG AND ABANDONMENT
PULL OR ALTER CASING		BING TEST AND CEMENT JOB	
	—	OTHER	
OTHER Frac Stimulat			
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703.			
1. MI and RU pulling unit.			
2. Pull rods and tubing.			
3. Frac down casing w/40,000 gallons refined oil and 50,000# sand.			
4. Run tubing and check sand fill.			
5. Run rods and put of	n pump.		
. Recover load.			
Put on production and test.			