

District I
1625 N. French Dr., Hobbs, NM 87240
District II
811 South First, Artesia, NM 87210
District III
1000 Rio Brazos Rd., Aztec, NM 87410
District IV
2040 South Pacheco, Santa Fe, NM 87505

OIL CONSERVATION DIVISION
2040 South Pacheco
Santa Fe, NM 87505

WELL API NO.	30-041-10168
5. Indicate Type of Lease	STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.	10047
7. Lease Name or Unit Agreement Name	Todd Lwr SA Unit Sec. 36
8. Well No.	5
9. Pool name or Wildcat	Todd Lower San Andres Assoc

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:
Oil Well ☐ Gas Well ☐ Other WIW - TA

2. Name of Operator
Saga Petroleum LLC

3. Address of Operator
415 W Wall, Suite 1900
Midland, TX 79701

4. Well Location
Unit Letter E : 1980 feet from the North line and 660 feet from the West line
Section 36 Township 7S Range 35E NMPM County ROOSEVELT

10. Elevation (Show whether DR, RKB, RT, GR, etc.)

11. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data


NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/> PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/> ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/> CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/> PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/> MULTIPLE COMPLETION <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER: <input type="checkbox"/>	OTHER: Set CIBP & TA <input checked="" type="checkbox"/>

12. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting and proposed work). SEE RULE 1103. For Multiple Completions: Attach diagram of proposed completion or recompletion.

6-13-2002 Unset Lock-set pkr, POOH w/tbg & pkr, PU 4-3/4" bit & scraper, RIH to 4080', circ hole w/fresh wtr, POOH wbit & scraper. RIH w/CIBP to 4077', set & POOH, LD tbg, NU WH, Run press test for TA

Press to 500 psi, held for 30 mins - good test - Chart attached

This Approval of Temporary
Abandonment Expires 6/18/07



I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Bonnie Husband TITLE Production Analyst DATE 06/17/2002

Type or print name Bonnie Husband
(This space for State use)

Telephone No. (915)684-4293

APPROVED BY _____ DATE 6/19/02
Conditions of approval, if any: **ORIGINAL SIGNED BY**
GARY W. WINK
OC FIELD REPRESENTATIVE II/STAFF MANAGER

5
C
<

